

FACILITY AUDIT REPORT
33 W. 11th Avenue
OHIO LEGAL CENTER
#193
SEPTEMBER 17, 1991

Prepared by:
The Ohio State University
Department of Physical Facilities
Division of Resource Management

TABLE OF CONTENTS

GENERAL BUILDING INFORMATION3
BUILDING SYSTEMS INFORMATION4
OHIO LEGAL CENTER NARRATIVE5
PROPOSED MAINTENANCE PROJECTS9
MAINTENANCE PROJECTS10
BUILDING EVALUATION SUMMARY11
 FOUNDATIONS12
 COLUMNS AND BEAMS13
 EXTERIOR WALLS14
 EXTERIOR WINDOWS & DOORS15
 ROOFING16
 PARTITIONS & DOORS17
 WALL FINISHES18
 FLOOR FINISHES19
 CEILINGS AND FINISHES20
 CONVEYING21
 MECHANICAL/PLUMBING22
 MECHANICAL/HEATING23
 COOLING & VENTILATING24
 ELECTRICAL/SERVICE & DISTRIBUTION25
 ELECTRICAL/LIGHTING & POWER26
 SAFETY STANDARDS27
 BUILDING PERIMETER EVALUATION28
BUILDING AUDIT METHODOLOGY29
ABBREVIATIONS31
APPENDIX32
 Building Floor Plans32
 C-1 Building Space Assignments32

GENERAL BUILDING INFORMATION

OHIO LEGAL CENTER #193

BUILDING ADDRESS: 33 WEST 11TH AVENUE

GROSS SQ. FT.: 24,411

NET ASSIGNABLE SQ. FT.: 16,358

MECHANICAL/CUSTODIAL AREA SQ. FT.: 2,758

YEAR OF CONSTRUCTION: 1962

YEAR OF LAST RENOVATION: N/A

NUMBER OF STORIES/BASEMENT: THREE (3) WITH A FULL BASEMENT

AIR CONDITIONING (Percentage): 100

CURRENT USE: BUILDING IS VACANT, BUT IS DESIGNED TO BE AN OFFICE BUILDING

TYPE OF CONSTRUCTION: REINFORCED CONCRETE STRUCTURE

ESTIMATED REPLACEMENT COST: \$2,353,000 *

BUILDING APPEARANCE: OUT OF DATE DECOR, BUT VERY FUNCTIONAL

HANDICAPPED ACCESSIBILITY: NONE, SOUTHEAST ENTRANCE DOOR IS AT GRADE LEVEL (NO STEPS), BUT DOOR DOES NOT HAVE AN AUTOMATIC OPENER.

INITIAL CONSTRUCTION QUALITY: GOOD

OVERALL BUILDING CONDITION: SATISFACTORY

NUMBER OF EXIT STAIRWAYS: TWO (2)

* Replacement Cost assigned January 1991 by The Office of Campus Planning and Space Utilization.

BUILDING SYSTEMS INFORMATION

OHIO LEGAL CENTER #193

HEATING:

Source GAS FIRED HOT WATER HEATING BOILER
Type Heating System RADIANT CEILING PANELS, FIN RADIATION, UNIT HEATERS
Steam (Line size, valve location) NONE
Building Htg Water (line size, valve location) NONE

VENTILATION SYSTEM: HIGH VELOCITY DUAL DUCT SYSTEM

COOLING:

Bldg % 100 Chillers CARRIER RECIPROCATING CHILLER (75 TONS)
Window Units N/A Thru-the-wall N/A Direct exp. units N/A

HVAC CONTROL SYSTEM: POWERS PNEUMATIC SYSTEM

ELECTRIC: Source Size(KVA) Primary/Secondary Switchgear & Main Disc. (Rm)
1. COLUMBUS & SOUTHERN 3 PHASE, 4 WIRE, 120/208 VOLTS, 800 AMPS, RM 1M

PLUMBING:

Water (size, valve location) 2 1/2" WATER SERVICE SOUTHEAST BASEMENT CORNER
Gas (size, valve location) 4 INCH LINE, OUTSIDE AT THE SOUTHEAST CORNER
Domestic Hot Water (size, valve location) 1" LINE IN BASEMENT ROOM 1M
Compressed Air (size, location) AIR COMPRESSOR FOR CONTROLS IN RM 1M

SEWERS: Storm COMBINATION 8" LINE ON SOUTHSIDE OF THE BUILDING

METERS:

Gas (size, location) 4" LINE, SOUTHEAST CORNER OF THE BUILDING
Water (size, location) 2" LINE AND METER ON EAST BASEMENT WALL
Electric (size, location) SOUTH WALL OF THE BASEMENT IN ROOM 1M

ALARM SYSTEMS:

Fire Alarm YES Panel Location SOUTH BASEMENT WALL ROOM 1M
Fire Pump N/A Pump Location N/A
Sprinklers N/A Panel Location N/A
Other Alarms NONE

ELEVATORS:

Number ONE Type (passenger, freight) PASSENGER
Manufacturer WESTINGHOUSE Size 2000 LBS.

EMERGENCY GENERATOR: Size NONE Location N/A

KEY BOX LOCATION: ENTRY WAY OF THE NORTH (FRONT) ENTRANCE

ASBESTOS SURVEY (1986):

ASBESTOS CONTAINING MATERIALS WERE IDENTIFIED IN THE HEAT EXCHANGER INSULATION AND INSULATION ON ELBOWS AND FITTINGS IN ROOM 1M.

OHIO LEGAL CENTER NARRATIVE

GENERAL

This Building Audit was conducted by Physical Facilities for the purpose of evaluating the present condition of the building for which Physical Facilities has a budgetary responsibility. This audit describes the current physical condition of the facility and identifies existing corrective maintenance and building component system replacement requirements.

It has been assumed that the program needs of the tenant departments are being met by the facility. In addition, this audit does not intend to assess the condition of this facility that is the budgetary responsibility of the tenant departments.

Audit objectives and methodology are described in greater detail in the "Building Audit Methodology" section of this report.

HISTORY

The construction of the Ohio Legal Center was completed in 1962. The office building was constructed for The Ohio Bar Association. The building has a full basement of 6515 square feet that was used for storage by The Ohio Bar Association. There is a landscaped courtyard with reflecting pool located off the main entrance and lobby.

The Ohio Bar Association moved out of the building earlier this year, and the building was acquired by The Ohio State University. The building is currently vacant. Some College of Law staff are being moved into the Ohio Legal Center. They will occupy part of the 3rd floor on a temporary basis. The basement is being remodeled to provide office and stockroom space for the new southeast area shop to be established in December, 1991.

PRIMARY SYSTEMS

The foundation, basement floor, and superstructure all appear to be in good condition. There are no signs of settlement or movement in the building foundation. The exterior closure, which consists of brick veneer, limestone panels, and aluminum window panels, shows no signs of structural problems. The exterior caulking is cracked and brittle and needs to be replaced. There is ivy growing on the east side of the building that should be removed.

The windows are aluminum single hung with spring balances. The windows all opened, and all of the balances were working. The windows are single glazed and a building improvement project is being proposed to replace these windows with a double glazed thermal break window. The entry doors are all aluminum with the exception of the steel double doors at the rear of the building that are steel. These doors need to be painted.

The roof on the Ohio Legal Center is the original one installed in 1962. While this roof is functioning satisfactorily, it has surpassed its useful expected life and will need to be replaced in the near future. A project has been proposed to replace this roof within the next five years.

SECONDARY SYSTEMS

The partitions, doors, walls, and ceilings are in good condition throughout the building. Several of the offices were recently painted. The corridors are a blue-grey glazed block that dates the decor of the building, but if cleaned would be in a like new condition.

The ceilings in the building are 12"x 12" metal pan ceiling tiles. The ceiling tiles, light fixtures, and registers are dirty and need to be cleaned. Other than being dirty, the ceilings throughout the building are in very good condition.

Composition floor tile has been installed in the corridors and office areas. The color of the tile cannot be matched, so replacement tiles are of a different color. Some of the offices on the 1st and 2nd floor have been carpeted, but the carpet is worn or damaged and needs to be replaced. The stairwells are constructed of metal framed stairs and terrazzo stair treads. The paint finish on the metal frame of the stairs is in fair condition.

SERVICE SYSTEMS

The major service systems at the Ohio Legal Center are 30 years old, but continue to function adequately. The elevator has a very good operating history. The cab does not have wheel chair access controls, but has both front and rear doors. There is no emergency telephone installed in the cab, so a project has been proposed to update this elevator.

The hot water heating system does a good job of heating the Ohio Legal Center. The plumbing for the domestic water system is operating adequately. The restroom fixtures were in good working order and no problems were observed. The basement has a sump pump and showed no signs of any moisture problems.

There is one (1) air handler system, a high velocity dual duct system, providing heating, cooling and ventilation to the building. The building is 100% air conditioned. The system components are 30 years old with the exception of the pneumatic controls that were installed in 1990.

No energy conservation changes have been incorporated in the Ohio Legal Center. A report was completed by Joseph Larabee in April, 1987 making certain recommendation for reducing energy costs, but none of these recommendations were adopted.

ELECTRICITY

The building is supplied with electricity by Columbus and Southern Electric Co. There is 800 amp electric service to the building. The utilization of the circuit breaker panels indicates that there is limited capacity to expand service in the building. A recent study to increase the reciprocating compressor from 75 to 100 horsepower noted that the building electrical service would have to be increased.

Building lighting is primarily fluorescent. The corridors, mechanical and storage rooms have incandescent lighting. These areas should be relamped with fluorescent fixtures to reduce building energy costs. All the lighting fixtures need to be cleaned.

The mechanical room in the basement has 9 different watt meter transducers for measuring electric usage. The transformer coils for these meters are sitting on the floor without any conduit protecting the wires. These coils should be removed or correctly installed.

SAFETY STANDARDS

The Ohio Legal Center is equipped with a manual fire alarm system. There are no hose cabinets or stand pipes in the building. There are portable fire extinguishers located on each floor. There are no emergency lights or lighted exit signs located in the building. These systems should be installed.

The Ohio Board of Regents Facilities Asbestos Inspection and Risk Assessment Program's report: Inventory of friable Asbestos-Containing Materials in Buildings of the Ohio State University (Main and Branch Campuses) and Recommendations for Corrective Action by PEI Associates, September 1986, located asbestos containing materials in the heat exchanger insulation and in the elbows & fittings insulation.

BUILDING PERIMETER

The sidewalks on 11th and along the parking area to the east are in good condition. The shrubs are overgrown and need to be trimmed back. The courtyard inside the fenced area has a reflective pool that needs to be repaired. This area needs to be improved by repairing the pool or filling it in so that plants could be grown in this area. The gravel walkways should be surfaced with concrete to provide access to the parking lot. A general trimming and clean-up of the shrubbery is needed.

The signage for the Ohio Legal Center is located on 11th Avenue and is engraved in the limestone front of the building. It would help identify the building better if an identification sign was added in front of the building on 11th Avenue.

A brick screen wall extends from the northeast corner of the building and extends to provide a circular screen for the flag pole located in the northeast corner of the property. The mortar joints and some brick have deteriorated and need to be repaired. A project has been proposed to repair this wall for \$9,500. Consideration should be given to eliminating the wall and opening up the area to improve visibility and security in the area.

CONCLUSION

The Ohio Legal Center building systems are functioning very effectively for a building that is 30 years old. The HVAC system and the plumbing system are operating adequately. The current requests for improvements to the building are for the upgrading of the building to meet new safety requirements, comply with handicap access requirements, and to improve energy conservation.

The office walls are being painted and some of the vinyl floor tile is being replaced, but the major building systems are operating effectively. It appears that very few repairs or replacements have been made since the original equipment was installed in 1962.

The installation of Direct Digital Control (DDC) system and the replacement of incandescent lights would be the first priority improvements to be incorporate to

reduce energy costs.

Major building components that are expected to fail and need replaced in the next few years are the roof and the cooling system. Replacement of the cooling system will necessitate some upgrades to the electric service to the building.

PROPOSED MAINTENANCE PROJECTS
(R&R or CAPITAL FUNDED)

Ohio Legal Center #193

A. Corrective Maintenance Projects:

- 1. Install exit lights & emergency lights.....\$25,000*
- 2. Remove Ivy from east side of the building and
cutout & replace all sealants.(11,880 SF)..... 29,000
Sub Total \$54,000

B. Building Improvement Projects:

- 1. Repair reflective pool and walks around pool.
Install new fence around the courtyard.....\$15,400.
- 2. Repair brick screen wall at northeast corner of
the building.....9,500*
- 3. Upgrade elevator to include wheelchair controls
and emergency telephone.....35,000
- 4. Energy Conservation Modifications:
 - (a) Replace incandescent lights with fluorescent
fixtures.....15,000
 - (b) Install DDC Controls to provide better temperature
control and night setback.....24,000
 - (c) Replace single glazed windows with insulated
double glazed windows.....57,200
- 5. Replace electric service with new 1200 amp service,
panel board and feeders.....12,775
Sub Total \$168,875

C. Building Component Replacements expected within the next 5 years:

- 1. Replace 8,344 SF of BUR roof.....\$65,000*
- 2. Replace existing reciprocating chiller and air cooled
cooled condensing unit with a new energy efficient unit.54,900
Sub Total \$119,900

Total Cost for all Projects = \$342,775

* These projects are currently on our departmental project list as either proposed or funded projects.

MAINTENANCE PROJECTS
(Less than \$5,000)

Ohio Legal Center #193

1. Paint steel doors at the rear of the building.
2. Glazed block corridor walls need to be washed.
3. Metal tile ceiling, light fixtures and registers need to be cleaned.
4. Install sign with address on 11th Avenue.
5. Trim shrubs and trees around the building and in the courtyard.
6. Remove the nine (9) Watt Meter Transducers that are improperly wired.

BUILDING EVALUATION SUMMARY

I. BUILDING INFORMATION

FAC # 193 FACILITY NAME: OHIO LEGAL CENTER
 DATE: 8-28-91 INSPECTOR: RDL
 YEAR CONSTRUCTED: 1962
 GROSS SQ FT: 24,411 NET SQ FT: 16,358
 REPLACEMENT COST \$ 2,353,000 X 97% = 2,282,410 *

II. COMPONENT RATING

COMPONENT	BUILDING COMPONENT PERCENTAGE OF TOTAL COST **	BUILDING COMPONENT REPLACEMENT COST *	CONDITION VALUE MULTIPLIER FOR BLDG. COMPONENT	BUILDING COMPONENT CURRENT VALUE
Foundation	4.00	91,296	0.90	82,166
Columns and Beams	14.37	327,982	0.90	295,184
Exterior Walls	8.51	194,233	0.83	161,213
Windows & Doors	4.16	94,948	0.80	75,958
Roofing	2.74	62,538	0.50	31,269
Partitions & Drs.	8.90	203,134	0.84	170,633
Wall Finishes	2.71	61,853	0.63	38,967
Floor Finishes	6.18	141,053	0.57	80,400
Ceilings & Finish	7.34	167,529	0.71	118,946
Conveying	3.81	86,960	0.68	59,133
Plumbing	2.22	50,670	0.84	42,563
Heating	8.96	204,504	0.80	163,603
Cooling & Vent.	6.91	157,715	0.50	78,858
Elec. Ser. & Dist	1.36	31,041	0.80	24,833
Lighting & Power	10.98	250,609	0.61	152,871
Safety Standards	6.85	156,345	0.63	98,497
TOTALS	100.00	2,282,410	11.54	1,675,094

III. BUILDING RATING SUMMARY

Overall Building Rating = 73.4 %

* Replacement Cost assigned January 1991 by The Office of Campus Planning and Space Utilization deducting 3% for furnishings and fixed equipment allocation.

** Percent allocation of each building component is calculated from The Means Standard Construction Cost data for College Classroom Buildings.

COLUMNS AND BEAMS

FAC # 193 DATE 8-29-91 INSPECTOR: RDL

A. SYSTEM DESCRIPTION

a. Columns and Beams:

	N/A	Sat	Att
Concrete-in-place <u>THROUGH OUT THE BUILDING</u>	[]	[X]	[]
Precast Concrete _____	[X]	[]	[]
Steel _____	[X]	[]	[]
Steel Fireproofing _____	[X]	[]	[]
Wood _____	[X]	[]	[]
Other _____	[X]	[]	[]

b. Floors:

Concrete Slab <u>BASEMENT AND THE FLOOR FOR EACH STORY</u>	[]	[X]	[]
Precast Slab _____	[X]	[]	[]
Metal Deck _____	[X]	[]	[]
Metal Deck w/concrete fill _____	[X]	[]	[]
Wood _____	[X]	[]	[]
Other _____	[X]	[]	[]

c. Roof System:

Flat <u>ALL THE ROOF AREAS ARE FLAT</u>	[]	[X]	[]
Pitched _____	[X]	[]	[]
Concrete <u>THE 3 STORY STRUCTURE ROOF DECK</u>	[]	[X]	[]
Steel <u>THE ONE STORY AREA AT THE ENTRANCE</u>	[]	[X]	[]
Wood _____	[X]	[]	[]
Other _____	[X]	[]	[]

B. COMMENTS:

THE COLUMNS AND BEAMS DO NOT SHOW ANY SIGNS OF DETERIORATION.

C. COMPONENT RATING: $(\underline{327,982}) \times (\underline{90.0\%}) = \underline{\$295,184}$

Possible	Condition	Component
Value	Value Multiplier	Value

EXTERIOR WINDOWS & DOORS

FAC # 193 DATE 8-29-91 INSPECTOR: RDL

A. SYSTEM DESCRIPTION

a. Windows type & number:	<u>N/A</u>	<u>Sat</u>	<u>Att</u>
Wood _____	[X]	[]	[]
Steel _____	[X]	[]	[]
Alum <u>DOUBLE HUNG WINDOWS</u>	[]	[X]	[]
Other _____	[X]	[]	[]
 b. Window glazing			
Single pane <u>ALL WINDOWS (5,980 SF OF GLASS & PANELS)</u>	[]	[X]	[]
Double pane _____	[X]	[]	[]
Other _____	[X]	[]	[]
 c. Doors type & number:			
Wood _____	[X]	[]	[]
Steel <u>DOUBLE DOORS AT THE SOUTH LOADING AREA</u>	[]	[]	[X]
Alum <u>ENTRY DOORS ON THE NORTH, SOUTH, AND EAST SIDE</u>	[]	[X]	[]
Other _____	[X]	[]	[]
 d. Shading Devices:			
Types <u>VENETIAN BLINDS AND DRAPERIES ARE USED</u>	[]	[X]	[]

B. COMMENTS:

1. ALL THE WINDOWS THAT WERE OPENED AND CLOSED OPERATED CORRECTLY.
2. THE STEEL DOORS AT THE LOADING AREA ARE RUSTED AND NEED TO BE PAINTED.

C. COMPONENT RATING: (94,948) x (80.0%) = \$75,958

Possible	Condition	Component
Value	Value Multiplier	Value

ROOFING

FAC # 193 DATE 8-29-91 INSPECTOR: RDL

A. SYSTEM DESCRIPTION

a. Roof Covering:

Built-up _____	[X]	[]	[]
Built-up w/gravel <u>A FEW AREAS SHOW SIGNS OF DETERIORATION</u>	[]	[X]	[]
Asphalt Shingle _____	[X]	[]	[]
Copper _____	[X]	[]	[]
Glass (Skylight) _____	[X]	[]	[]
Slate _____	[X]	[]	[]
Spanish Tile _____	[X]	[]	[]
Metal _____	[X]	[]	[]
Other _____	[X]	[]	[]

b. Flashing:

Base & Counter <u>HAS BEEN COVERED WITH MASTIC</u>	[]	[X]	[]
Cap _____	[X]	[]	[]
Through Wall _____	[X]	[]	[]
Valley & Ridge _____	[X]	[]	[]

c. Gravel Stop & Edge Strips:

Type <u>ALUMINUM AROUND THE EXTERIOR OF THE BUILDING</u>	[]	[X]	[]
--	-----	-----	-----

e. Drainage:

Gutters _____	[X]	[]	[]
Drains <u>GOOD SLOPE TO ROOF DRAINS</u>	[]	[X]	[]
Scuppers _____	[X]	[]	[]
Downspouts _____	[X]	[]	[]

f. Parapets:

Concrete _____	[X]	[]	[]
Brick _____	[X]	[]	[]
Block _____	[X]	[]	[]
Precast _____	[X]	[]	[]
Other _____	[X]	[]	[]

g. Insulation:

Type <u>2" OF RIGID INSULATION ON CONCRETE DECK</u>	[]	[X]	[]
---	-----	-----	-----

B. COMMENTS

1. THE ROOF COVER IS 30 YEARS OLD, BUT ONLY SHOWS SIGNS OF DETERIORATION AT A FEW SMALL AREAS. THERE ARE NO SIGNS OF ANY LEAKAGE ON THE INSIDE OF THE BUILDING. THERE IS 8,344 SQ. FT. OF ROOF AREA.
2. WE ARE RECOMMENDING THAT THIS ROOF COVER WILL NEED TO BE REPLACED IN THE NEXT 3 TO 6 YEARS.

C. COMPONENT RATING: $(\underline{62,538}) \times (\underline{50.0\%}) = \underline{\$31,269}$

Possible	Condition	Component
Value	Value Multiplier	Value

FLOOR FINISHES

FAC # 193 DATE 8=30-91 INSPECTOR: RDL

A. SYSTEM DESCRIPTION

	N/A	Sat	Att
a. Carpet:			
Rolled <u>RMS 101, 105-108, 115, 117, 209-214 NEEDS REPLACED</u>	[]	[]	[X]
Tile _____	[X]	[]	[]
b. Composition:			
Epoxy _____	[X]	[]	[]
Synthetic _____	[X]	[]	[]
Other _____	[X]	[]	[]
c. Concrete Topping:			
Clear Sealant <u>BASEMENT FLOOR</u>	[]	[X]	[]
Abrasive _____	[X]	[]	[]
Epoxy _____	[X]	[]	[]
Aggregate _____	[X]	[]	[]
d. Resilient:			
Vinyl Tile <u>RMS 109, 202-204, 301-304, 309-312</u>	[]	[]	[X]
Linoleum _____	[X]	[]	[]
Vinyl _____	[X]	[]	[]
Rubber _____	[X]	[]	[]
Cork _____	[X]	[]	[]
e. Ceramic Tile <u>CERAMIC MOSAIC TILE IN RESTROOMS</u>	[]	[X]	[]
f. Masonry _____	[X]	[]	[]
g. Terrazzo <u>MAIN LOBBY AND GROUND FLOOR OF SE STAIRWELL</u>	[]	[X]	[]
h. Wood _____	[X]	[]	[]
i. Metal _____	[X]	[]	[]

B. COMMENTS

1. ALL CARPETED AREAS NEED TO HAVE THE CARPET REPLACED.
2. FLOOR TILE IN ROOM 311 NEEDS TO BE REPLACED.

C. COMPONENT RATING: $\left(\frac{141,053}{\text{Possible Value}} \right) \times \left(\frac{57.0\%}{\text{Condition Value Multiplier}} \right) = \frac{\$80,400}{\text{Component Value}}$

CONVEYING

FAC # 193 DATE 8-30-91 INSPECTOR: RDL

A. SYSTEM DESCRIPTION

a. Elevators:

	<u>N/A</u>	<u>Sat</u>	<u>Att</u>
Number <u>ONE (1)</u>	[]	[X]	[]
Type <u>PASSENGER</u>	[]	[X]	[]
Speed <u>100 fpm</u>	[]	[X]	[]
Capacity (lbs) <u>2,000 lbs.</u>	[]	[X]	[]
Dimensions <u>4' X 5'</u>	[]	[X]	[]
Door Operation:			
Center _____	[X]	[]	[]
To Side <u>ELEVATOR HAS FRONT AND REAR DOORS</u>	[]	[X]	[]

b. Lifts and Hoists:

Number _____	[X]	[]	[]
Type _____	[X]	[]	[]

c. Moving Stairs and Walks:

Number _____	[X]	[]	[]
Type _____	[X]	[]	[]

d. Conveyors:

Number _____	[X]	[]	[]
Type _____	[X]	[]	[]

e. Pneumatic Tubes:

Number _____	[X]	[]	[]
Type _____	[X]	[]	[]

B. COMMENTS:

ELEVATOR NEEDS TO BE UPGRADED WITH HANDICAP CONTROLS AND EMERGENCY TELEPHONE COMMUNICATIONS.

C. COMPONENT RATING: $\frac{(86,960)}{\text{Possible Value}} \times \frac{(68.0\%)}{\text{Condition Value Multiplier}} = \frac{\$59,133}{\text{Component Value}}$

MECHANICAL/PLUMBING

FAC # 193 DATE 9-3-91 INSPECTOR: RDL

A. SYSTEM DESCRIPTION

	<u>N/A</u>	<u>Sat</u>	<u>Att</u>
a. Services Available:			
Cold Water <u>COPPER LINES</u>	[]	[X]	[]
Hot Water <u>COPPER LINES</u>	[]	[X]	[]
Acid Waste _____	[X]	[]	[]
Oxygen _____	[X]	[]	[]
Natural Gas <u>LOCATED IN THE MECHANICAL ROOM 1M ONLY</u>	[]	[X]	[]
Vacuum _____	[X]	[]	[]
Distilled Water _____	[X]	[]	[]
Compressed Air <u>COMPRESSOR LOCATED IN THE BASEMENT</u>	[]	[X]	[]
Other _____	[X]	[]	[]
b. Piping & Fittings:			
Cast Iron <u>WASTE DRAIN LINES</u>	[]	[X]	[]
Copper Tubing <u>WATER SUPPLY LINES</u>	[]	[X]	[]
Plastic _____	[X]	[]	[]
Steel <u>GAS SUPPLY LINES</u>	[]	[X]	[]
Glass _____	[X]	[]	[]
c. Water Heaters:			
Electric _____	[X]	[]	[]
Gas <u>NEW HEATER INSTALLED IN 1989</u>	[]	[X]	[]
Oil _____	[X]	[]	[]
Steam Converter _____	[X]	[]	[]
Other _____	[X]	[]	[]
d. Drainage:			
Storm Drains _____	[]	[X]	[]
Sanitary Drainage _____	[]	[X]	[]
Combined Storm/San. _____	[X]	[]	[]
Floor Drains _____	[]	[X]	[]
e. Fixtures:			
Water Closets <u>10 LOCATED IN RESTROOMS</u>	[]	[X]	[]
Urinals <u>3 FIXTURES, ONE ON EACH FLOOR</u>	[]	[X]	[]
Lavatories <u>7 FIXTURES IN THE BUILDING</u>	[]	[X]	[]
Showers _____	[X]	[]	[]
Kitchen Sinks <u>1 LOCATED IN ROOM 109</u>	[]	[X]	[]
Service Sinks <u>4 LOCATIONS, ONE ON EACH FLOOR</u>	[]	[X]	[]
Drinking Fountains _____	[X]	[]	[]
Electric Water Coolers <u>3 FIXTURES, ONE ON EACH FLOOR</u>	[]	[X]	[]
f. Sprinkler Systems:			
Wet _____	[X]	[]	[]
Dry _____	[X]	[]	[]
Water Storage/Supply _____	[X]	[]	[]
g. Standpipe Systems:			
Wet _____	[X]	[]	[]
Dry _____	[X]	[]	[]
Valves _____	[X]	[]	[]
Hose Cabinets _____	[X]	[]	[]

B. COMMENTS:

NO DEFICIENCIES WERE OBSERVED WITH THE PLUMBING SYSTEM.

C. COMPONENT RATING: $\left(\frac{50,670}{\text{Possible Value}} \right) \times \left(\frac{84.0\%}{\text{Condition Value Multiplier}} \right) = \frac{\$42,563}{\text{Component Value}}$

MECHANICAL/HEATING

FAC # 193 DATE: 9-3-91 INSPECTOR: RDL

A. SYSTEM DESCRIPTION

a. Heat Source:	N/A	Sat	Att
Central Plant Steam _____	[X]	[]	[]
Central Plant Hot Water _____	[X]	[]	[]
Boilers: Type <u>WEIL-MCLAIN INSTALLED IN 1988</u>	[]	[X]	[]
Size <u>BG 688 W-S</u>	[]	[X]	[]
Furnace: Type _____	[X]	[]	[]
Size _____	[X]	[]	[]
Heat Pump: Type _____	[X]	[]	[]
Size _____	[X]	[]	[]
Burners: gas _____	[X]	[]	[]
oil _____	[X]	[]	[]

b. System Type:			
Steam _____	[X]	[]	[]
Hot Water <u>NEW GAS FIRED HOT WATER TANK INSTALLED IN 1988</u>	[]	[X]	[]
Air _____	[X]	[]	[]
Electric _____	[X]	[]	[]
Solar _____	[X]	[]	[]
Other _____	[X]	[]	[]

c. Space Equipment:			
Radiators _____	[X]	[]	[]
Convectors _____	[X]	[]	[]
Finned Tube <u>LOCATED IN HOT DECK OF VENTILATION SYSTEM</u>	[]	[X]	[]
Baseboard _____	[X]	[]	[]
2-Pipe Fan Coil <u>STAIRWELLS HAVE UNITS AT ENTRANCES</u>	[]	[X]	[]
Unit Ventilators _____	[X]	[]	[]
Multizone _____	[X]	[]	[]
Double Duct <u>OFFICE AREAS HAVE A HIGH VELOCITY DUAL DUCT</u>	[]	[]	[X]
Terminal Reheat _____	[X]	[]	[]
Other <u>CEILING HAS RADIANT HOT WATER HEATING PANELS</u>	[]	[X]	[]

d. Control Type:			
Pneu <u>POWERS PNEUMATIC CONTROLS</u>	[]	[]	[X]
Electric _____	[X]	[]	[]
Electronic _____	[X]	[]	[]
DDC _____	[X]	[]	[]
Manual Valves _____	[X]	[]	[]

B. COMMENTS:

NO DEFICIENCIES WERE OBSERVED IN HEATING SYSTEM. THERE HAVE NOT BEEN ANY ENERGY CONSERVATION MODIFICATIONS MADE TO THIS BUILDING. A PROJECT IS PROPOSED TO INCORPORATE DDC CONTROLS AND REPLACE INCANDESCENT LIGHTS WITH FLUORESCENT FIXTURES.

C. COMPONENT RATING: $(\underline{204,504}) \times (\underline{80.0\%}) = \underline{\$163,603}$

Possible Condition Component

Value Value Multiplier Value

COOLING & VENTILATING

FAC # 193 DATE: 9-3-91 INSPECTOR: RDL

A. SYSTEM DESCRIPTION

	N/A	Sat	Att
a. System:			
Type <u>HIGH VELOCITY DUAL DUCT WITH A DX COOLING COIL</u>	[]	[]	[X]
Capacity <u>APPROX. 75 TONS</u>	[]	[]	[X]
b. Chillers:			
Centrifugal _____	[X]	[]	[]
Reciprocating <u>ACME, MODEL #5H89-338</u>	[]	[]	[X]
Absorption _____	[X]	[]	[]
c. Cooling Towers:			
Type _____	[X]	[]	[]
Capacity _____	[X]	[]	[]
d. Condensers: <u>AIR CONDENSER, BUFFALO FORGE #60L 17950</u>	[]	[]	[X]
e. Space Equipment:			
Direct Expansion -			
Window units _____	[X]	[]	[]
Thru-the-wall _____	[X]	[]	[]
Single zone _____	[X]	[]	[]
Single zone con. vol _____	[X]	[]	[]
Other _____	[X]	[]	[]
Air/Water -			
2-pipe fan coil _____	[X]	[]	[]
Unit ventilators _____	[X]	[]	[]
Terminal Reheat _____	[X]	[]	[]
Variable volume _____	[X]	[]	[]
Dual Duct _____	[X]	[]	[]
f. Special Systems:			
Type <u>DRAFT FAN FOR FIREPLACE IN 101</u>	[]	[X]	[]
Capacity _____	[X]	[]	[]
g. Control Systems:			
Pneu <u>POWERS SYSTEM</u>	[]	[X]	[]
Electric _____	[X]	[]	[]
Electronic _____	[X]	[]	[]
h. Fans:			
Exhaust <u>FOUR (4) FANS</u>	[]	[X]	[]
Recirculating <u>TWO (2) FANS</u>	[]	[X]	[]

B. COMMENTS:

THE RECIPROCATING COMPRESSOR IS CURRENTLY BEING REPAIRED. A NEW DISCONNECT BREAKER AND FAN BELT PULLEYS ARE BEING INSTALLED.

C. COMPONENT RATING: $\left(\frac{157,715}{\text{Possible Value}} \right) \times \left(\frac{50.0\%}{\text{Condition Value Multiplier}} \right) = \frac{\$78,858}{\text{Component Value}}$

ELECTRICAL/SERVICE & DISTRIBUTION

FAC # 193 DATE: 9-3-91 INSPECTOR: RDL

A. SYSTEM DESCRIPTION

(a) Service:

Substation COLUMBUS & SOUTHERN ELECTRIC
Primary Voltage
Transformer:
 Manufacture Type KVA Secondary Voltages
 N/A N/A N/A 3 PHASE, 120/208 VOLTS

(b) Distribution System:

Panelboard (type) Federal Pacific (F.O. P15011)
Voltage 120/208 Volts, 3 Phase, 4 Wire
Amperage 800 AMPS
Conduit n/a
Conductor n/a
Wire (type) Copper
Armored Cable n/a
Other n/a

(c) Emergency System:

General or (type & capacity) NONE

B. COMMENTS:

ELECTRIC SERVICE IS CLOSE TO BEING FULLY UTILIZED. NEW SERVICE WILL HAVE TO BE RUN IF R&R PROJECT TO INCREASE CHILLER HORSE POWER IS FUNDED.

C. COMPONENT RATING: $(\underline{31,041}) \times (\underline{80.0\%}) = \underline{\$24,833}$
 Possible Condition Component
 Value Value Multiplier Value

ELECTRICAL/LIGHTING & POWER

FAC # 193

DATE: 9-3-91

INSPECTOR: RDL

A. SYSTEM DESCRIPTION

a. Lighting (lamp type):

	<u>N/A</u>	<u>Sat</u>	<u>Att</u>
Fluor <u>USED IN OFFICE AREAS (FIXTURES ARE DIRTY)</u>	[]	[]	[X]
Incand <u>USED IN CORRIDORS & RMS. 101 & 115</u>	[]	[X]	[]
HID _____	[X]	[]	[]
Other _____	[X]	[]	[]

b. Receptacles & Switches

Type & Capacity <u>STANDARD GROUNDED RECEPTACLES</u>	[]	[X]	[]
--	-----	-----	-----

c. Special:

Baseboard Heat _____	[X]	[]	[]
Lightning Protection _____	[X]	[]	[]
Communication & Alarm _____	[X]	[]	[]
Data Systems _____	[X]	[]	[]

B. COMMENTS:

1. THE INCANDESCENT LIGHTS SHOULD BE REPLACED WITH FLUORESCENT FIXTURES TO CONSERVE ENERGY.
2. THE FLUORESCENT FIXTURES IN THE OFFICE AREAS NEED TO BE CLEANED.

C. COMPONENT RATING: $\frac{(\underline{250,609})}{\text{Possible Value}} \times \frac{(\underline{61.0\%})}{\text{Condition Value Multiplier}} = \underline{\$152,871}$ $\frac{\text{Component Value}}$

SAFETY STANDARDS

FAC # 193 DATE: 9-3-91 INSPECTOR: RDL

A. SYSTEM DESCRIPTION

(a) Exits:

Stair Construction:	N/A	SAT	ATT
concrete _____	[X]	[]	[]
steel <u>STEEL FRAME, TILE TREADS</u>	[]	[X]	[]
wood _____	[X]	[]	[]
Number of exits <u>TWO (2) STAIRWELL EXITS</u>			

(b) Fire Rating:

Construction Type: I X II ___ III ___ IV ___ V ___ VI ___
 Building Height: 36 FEET 3 STORIES

(c) Extinguishing Systems:

Portable _____	[]	[X]	[]
Standpipe _____	[X]	[]	[]
Hose Cabinets _____	[X]	[]	[]
Sprinklers _____	[X]	[]	[]
Suppression _____	[X]	[]	[]
Other _____	[X]	[]	[]

(d) Detection & Alarm Systems:

Manual Alarm _____	[]	[X]	[]
Annunciator _____	[X]	[]	[]
Smoke Detectors _____	[X]	[]	[]

(e) Lighting Systems:

Exit Signs _____	[]	[X]	[]
Exit Lighting _____	[X]	[]	[]
Emergency Lighting _____	[X]	[]	[]
Emergency Generator _____	[X]	[]	[]

B. COMMENTS:

BUILDING DOES NOT COMPLY WITH CURRENT SAFETY CODE. EMERGENCY LIGHTS AND POWER SYSTEMS NEED TO BE ADDED.

C. COMPONENT RATING: (156,345) x (63.0%) = \$98,497
 Possible Condition Component
 Value Value Multiplier Value

BUILDING PERIMETER EVALUATION

FAC # 193 DATE: 9-3-91 INSPECTOR: 9-1-91

A. SYSTEM DESCRIPTION

	N/A	Sat	Att
1. Structural Access:			
Driveway <u>LOCATED ON EAST AND SOUTH SIDES OF THE BUILDING</u>	[]	[X]	[]
Loading Dock <u>NONE, DELIVERY DOOR AT REAR</u>	[X]	[]	[]
Sidewalks			
Front <u>ALONG 11TH AVENUE</u>	[]	[X]	[]
Side <u>NEXT TO PARKING AREA</u>	[]	[X]	[]
Rear <u>DOUBLE DOORS FOR DELIVERIES</u>	[]	[X]	[]
Steps			
Front <u>MARBLE AT FRONT DOOR</u>	[]	[X]	[]
Side _____	[X]	[]	[]
Rear _____	[X]	[]	[]
Handicap Ramp <u>NONE AVAILABLE</u>	[]	[]	[X]
2. Lawn and Landscaping:			
Lawn <u>VERY DRY WITH SOME WEEDS</u>	[]	[X]	[]
Shrubs <u>OVERGROWN, NEED TO BE TRIMMED</u>	[]	[]	[X]
Trees <u>NEED TO BE PRUNED, SOME BRANCHES OVERHANG ROOF</u>	[]	[]	[X]
Undesirable Insect <u>NONE OBSERVED</u>	[]	[X]	[]
Bedding Material <u>MULCH</u>	[]	[X]	[]
Watering System _____	[X]	[]	[]
3. General Site Information:			
Signage <u>OHIO LEGAL NAME IS ENGRAVED IN BUILDING FRONT</u>	[]	[]	[X]
Address Identification <u>NONE</u>	[]	[]	[X]
Security Lights <u>NONE</u>	[]	[]	[X]
Street Lights <u>ON 11TH AVENUE</u>	[]	[X]	[]
Drainage _____	[]	[X]	[]
Storm Drains _____	[]	[X]	[]

B. COMMENTS:

1. THE CHAIN LINK FENCE AROUND THE COURTYARD NEEDS TO BE REPLACED.
2. THE REFLECTIVE POOL IN THE COURT YARD NEEDS THE CERAMIC TILE REPAIRED AND REPLACED. THE WALKS IN THE COURT YARD ARE GRAVEL.

**The Ohio State University
Department of Physical Facilities
BUILDING AUDIT METHODOLOGY**

1. BUILDING AUDIT PROGRAM OBJECTIVE

To provide a building-by-building inventory, including maintenance deficiencies that currently exist, for the 172 OSU buildings that the Department of Physical Facilities is budgetarily responsible. These audits will be used to establish repair and renovation projects, budget cost estimates for these projects, and overall levels of required maintenance funding.

2. BUILDING AUDIT APPROACH

A five-step procedure is used to meet the program objectives:

1. Collect Historical and Inventory Data on each building.
2. Interview Building Occupants.
3. Perform a Building Inspection.
4. Complete Building Evaluation Forms.
5. Issue Written Report.

3. DATA ORGANIZATION

The data collected is stored by hard copy with field notes in a building file established for each building. The report data is being stored in a database program that allows retrieval of specific data as it is needed. The "Building Evaluation" forms contain ratings for the condition of each building component and a description of any deficiencies for those components. The "Building Information" sheets provide data on the utilities to the buildings and the type of systems in each building.

4. COST ESTIMATES

Costs are for budgeting purposes only and are based on The Means Standard Construction Cost data, auditor experience, industry sources and OSU project cost data. Costs are reported current to the year of the audit. The building component values assigned in the "Building Evaluation" forms are not cost estimates. These values are calculated from the replacement cost provided by The Office of Campus Planning and Space Utilization for each OSU building. This building replacement cost is allocated to each building component to provide an estimated value for each component. Project cost estimates will exceed the building component values in most situations because of tear-out, handling and site limitations that occur in building component replacement projects.

5. DATA USAGE

Repair and Renovation Projects: provided to assist in the budgeting process for the Department of Physical Facilities.

Building Evaluation: provided to give a numerical rating for each building on campus quantifying its percentage of deficiency.

6. LIMITATIONS

(1) All inspections are visual and do not include physical tests, instrumentation or metering measurements, sampling, or monitoring.

(2) Only random typical offices or laboratories are entered. Typical spaces are deemed to be representative of average conditions throughout each building.

(3) The scope of the analysis does not include complete OSHA, energy, or physical impaired access study. Buildings and components are inspected for condition and general safety requirements rather than specialized code conformance.

(4) It is assumed that the buildings inspected were approved by the State of Ohio Division of Factory and Building Inspection at the time of construction. The recommendations listed in the reports are not an attempt to bring these existing buildings up to present day code standards. Rather, the intent is to eliminate obvious problems and to upgrade the buildings in a reasonable manner in regard to occupant safety.

(5) Cost estimates are in current year dollars and include contractor mark-ups, construction administration costs, and architectural/engineering costs where applicable. Escalation factors must be applied for future work. Combining of projects should serve to decrease costs. These estimates are strictly for purposes of budgeting, and final pricing will be required when the specific scope of work for the project is defined.

(6) The building inspections are defined to include the following:

(a) Includes general repainting and redecorating, wholesale replacement of building and system components. Ongoing maintenance, replacement and renovation projects are not included.

(b) Includes exterior building walls and attached items.

(c) Includes the first step up at all entries. Ramps outside the buildings are included; the steps and walks up to the ramps are not included.

(d) Blinds, drapes, light bulbs, and movable furniture are not included.

(e) Fixed equipment inside the buildings that is installed and maintained by a specific academic department or using agency is not included.

(f) Utility lines supplying the buildings are not included.

(g) The program needs of the using department are assumed to be satisfied. No consideration has been given to anticipate any changes in current occupant space needs.

ABBREVIATIONS

ATT.....	ATTENTION NEEDED
BLDG.....	BUILDING
BUR.....	BUILT UP ROOF
DD.....	DUAL DUCT AIR HANDLING SYSTEM
DDHV.....	DUAL DUCT HIGH VELOCITY
DHWR.....	DOMESTIC HOT WATER RETURN
DHWS.....	DOMESTIC HOT WATER SUPPLY
DX.....	DIRECT EXPANSION AIR CONDITIONER
FPM.....	FEET PER MINUTE
HID.....	HIGH INTENSITY DISCHARGE LIGHT
HVAC.....	HEATING, VENTILATING AND AIR CONDITIONING SYSTEM
KV.....	KILOVOLTS
KVA.....	KILOVOLTS AMPS
KW.....	KILOWATTS
LC.....	LIQUID COOLED
MZ.....	MULTIZONE AIR HANDLING SYSTEM
N/A.....	NOT APPLICABLE
PSI.....	POUNDS PER SQUARE INCH
RM.....	ROOM
SAT.....	SATISFACTORY
SR.....	STEAM RETURN LINE
SS.....	STEAM SUPPLY LINE
TR.....	TERMINAL REHEAT AIR HANDLING SYSTEM
V.....	VOLTS
VAV.....	VARIABLE AIR VOLUME SYSTEM

APPENDIX

Building Floor Plans
C-1 Building Space Assignments

Worksheet

CALCULATION OF BUILDING COMPONENT PERCENTAGE OF TOTAL COST

OHIO LEGAL CENTER

#193

DATE: 9-5-91

MEANS SQUARE FOOT COSTS

BUILDING SYSTEM	CLASS	LAB.	OFFICE	SUBJECT	% TOTAL
Foundations	2.85	8.61	2.14	2.14	3.99
Columns and Beams	7.70	4.73	6.33	7.70	14.37
Exterior Walls	1.63	2.94	4.56	4.56	8.51
Ext. Windows & Drs.	2.23	2.28	1.29	2.23	4.16
Roofing	1.47	3.01	0.97	1.47	2.74
Partitions & Doors	4.77	5.87	3.76	4.77	8.90
Wall Finishes	1.46	2.96	1.45	1.45	2.71
Floor Finishes	2.76	3.31	4.28	3.31	6.18
Ceilings & Finish	3.93	3.93	3.93	3.93	7.34
Conveying	0.92	0.00	2.04	2.04	3.81
Plumbing	4.54	12.10	1.19	1.19	2.22
Heating	4.80	4.80	4.80	4.80	8.96
Cooling & Vent.	5.51	5.51	3.70	3.70	6.91
Elec. Ser. & Dist.	0.95	0.56	0.73	0.73	1.36
Lighting & Power	6.39	5.50	5.88	5.88	10.98
Safety Standards	3.67	2.66	0.31	3.67	6.85
TOTAL	55.58	68.77	47.36	53.57	99.99

Worksheet

CALCULATION OF THE CONDITION VALUE MULTIPLIER

Ohio Legal Center #193

DATE: 9-5-91

	Expect Life	Age	Age Condition Value*	Perf Rate	Performance Condition Value**	Component Condition Value
Foundation	100	30	0.23	1.00	0.67	0.90
Column & Beams	100	30	0.23	1.00	0.67	0.90
Exterior Walls	75	30	0.20	0.95	0.63	0.83
Windows & Doors	60	30	0.17	0.95	0.63	0.80
Roofs	30	30	0.00	0.75	0.50	0.50
Partitions	60	30	0.17	1.00	0.67	0.84
Wall Finishes	15	30	0.00	0.95	0.63	0.63
Floor Finishes	60	30	0.17	0.60	0.40	0.57
Ceiling & Finish	40	30	0.08	0.95	0.63	0.71
Conveying	40	30	0.08	0.90	0.60	0.68
Plumbing	60	30	0.17	1.00	0.67	0.84
Heating	50	30	0.13	1.00	0.67	0.80
Cooling & Vent.	30	30	0.00	0.75	0.50	0.50
Electric Serv.	50	30	0.13	1.00	0.67	0.80
Lighting & Power	40	30	0.08	0.80	0.53	0.61
Safety Standards	25	30	0.00	0.95	0.63	0.63

* The age condition value is column (C-B) x 33.33%.

** The performance condition value is column E x 67.77%.