

FACILITY AUDIT REPORT  
BAKER SYSTEMS ENGINEERING, Bldg 280  
MAY 26, 1994

Prepared by:  
James P. Hertenstein  
Division of Resource Management  
Department of Physical Facilities  
The Ohio State University

Table of Contents

EXECUTIVE SUMMARY & PROJECT LIST FOR BAKER SYSTEMS ENG BLDG..... 3  
GENERAL BUILDING INFORMATION ..... 4  
BUILDING SYSTEMS INFORMATION ..... 5  
BAKER SYSTEMS ENGINEERING BUILDING NARRATIVE ..... 6  
BUILDING EVALUATION SUMMARY ..... 10  
    FOUNDATIONS ..... 11  
    COLUMNS AND BEAMS ..... 12  
    EXTERIOR WALLS ..... 13  
    EXTERIOR WINDOWS & DOORS ..... 14  
    ROOFING..... 15  
    PARTITIONS & DOORS ..... 16  
    WALL FINISHES ..... 17  
    FLOOR FINISHES ..... 18  
    CEILINGS AND FINISHES ..... 19  
    CONVEYING ..... 20  
    MECHANICAL/PLUMBING..... 21  
    MECHANICAL/HEATING ..... 22  
    COOLING & VENTILATING..... 23  
    ELECTRICAL/SERVICE & DISTRIBUTION..... 24  
    ELECTRICAL/LIGHTING & POWER ..... 25  
    SAFETY STANDARDS ..... 26  
    BUILDING PERIMETER EVALUATION ..... 27  
BUILDING AUDIT METHODOLOGY ..... 28  
ABBREVIATIONS ..... 30  
APPENDIX ..... 31  
    Reduced-Scale Building Floor Plans  
    C-1 Building Space Assignments

**EXECUTIVE SUMMARY AND PROJECT LIST FOR  
BAKER SYSTEMS ENGINEERING BUILDING**

This 26-year-old building is in good condition with a few exceptions. The exterior is in good condition and was recently cleaned and resealed. Interior finishes are sturdy but are beginning to show some signs of age. The building sustains high levels of traffic and the stairways and lower stairway walls require attention. The roof is original and while there have been few leaks, the cover is beginning to deteriorate requiring replacement within the next five years. The elevators located in this building are heavily utilized. The Department of Physical Facilities has proposed a project to upgrade and modernize them.

The main problem with this building has been the poor cooling of the central areas. This has resulted from an increased heat load from added computers exacerbated by energy conservation measures that reduced air flow and an insufficient supply of chilled water. Plans should be made to utilize the central chilled water plant being planned for the School of Business Complex or to replace the existing absorption chiller with a new centrifugal system. Air flow can then be increased to the interior sections of the building which have been undercooled.

**PROPOSED MAINTENANCE PROJECTS:**

| <b>A. Corrective Maintenance Projects:</b>                                |                      | <b>Control #</b> |
|---|----------------------|------------------|
| 1. Waterproof Mechanical Room Floor.....                                  | \$25,000             | 0409             |
| 2. Paint stairways & clean hallway<br>ceilings.....                       | 22,350               | 2279             |
| 3. Upgrade/Modernize Elevators  | ... <u>\$210,000</u> | 1950             |
| <b>Sub Total</b>  |                      | <b>\$257,350</b> |
| <br><b>B. Building Improvement/Addition Project:</b>                      |                      |                  |
| 1. Increase chilled water supply and<br>air-handling capacity .....       | <u>\$215,000</u>     | 2280             |
| <b>Sub Total</b>  |                      | <b>\$215,000</b> |
| <b>C. Projected (over the next 5 yrs) Component Replacement Projects:</b> |                      |                  |
| 1. Replace built-up roofing.....  | \$108,200            | 2281             |
| <br><b>Total cost for estimated projects =</b>                            | <br><b>\$580,550</b> |                  |

20 MAY 94

GENERAL BUILDING INFORMATION

BAKER SYSTEMS ENGINEERING #280

BUILDING ADDRESS: 1971 NEIL AVENUE

GROSS SQ. FT.: 114,888

NET ASSIGNABLE SQ. FT.: 70,404

MECHANICAL/CUSTODIAL AREA SQ. FT.: 16,690

YEAR OF CONSTRUCTION: 1968

YEAR OF LAST RENOVATION: N/A

NUMBER OF STORIES/BASEMENT: 6 FLOORS AND A BASEMENT

AIR CONDITIONING (Percentage): 85%

CURRENT USE: OFFICES, CLASSROOMS, LABS AND COMPUTER OPERATIONS

TYPE OF CONSTRUCTION: REINFORCED CONCRETE FRAME WITH MASONRY EXTERIOR

ESTIMATED REPLACEMENT COST: 17,266,000 \*

WHEELCHAIR ACCESSIBILITY: MAIN ENTRANCE AT THE SOUTH EAST CORNER IS AT GRADE LEVEL. THREE ELEVATORS ALLOW ACCESS TO ALL FLOORS.

OVERALL BUILDING CONDITION: SATISFACTORY\*\*

NUMBER OF EXIT STAIRWAYS: 3

\* Replacement Cost assigned Jun, 1993 by The Office of Campus Planning and Space Utilization.

\*\* Office of Campus Planning and Space Utilization C-1 Report Condition Code.

**BUILDING SYSTEMS INFORMATION**

BAKER SYSTEMS ENGINEERING # 280

**HEATING:**

Source STEAM FROM THE UNIVERSITY POWER PLANT TO LOCAL CONVERTERS  
Type Heating System HOT WATER  
Steam (Line size, valve location) 4" SUPPLY & 3" COND RETURN, 064M  
Building Htg Water (line size, valve location) LOCAL CONVERTERS IN 544M

**VENTILATION SYSTEM:**

MODIFIED DDHV-MOST OF BLDG, SINGLE DUCT LIQUID CHILLED, SPLIT DX SYSTEMS

**COOLING:**

Bldg % 85 Chillers 173 T ABSORPTION, 175T ELECTRIC CENTRIFUGAL  
Window Units 0 Thru-the-wall 0 Direct exp. units 8

**HVAC CONTROL SYSTEM:**

CENTRAL DIRECT DIGITAL CONTROL (CSI 7700)

**ELECTRIC:** Source Size(KVA) Primary/Secondary Switchgear & Main Disc. (Rm)

|                      |     |                    |      |
|----------------------|-----|--------------------|------|
| 1. BUCKEYE PGN5/PGS5 | 750 | 13,200/(208/120)   | 060M |
| 2. BUCKEYE PGN5/PGS5 | 750 | 13,200/(240 DELTA) | 060M |

**PLUMBING:**

Water (size, valve location) 6", 064M  
Gas (size, valve location) 2", 064M  
Domestic Hot Water (size, valve location) 3" SUPPLY, 1-1/4" RETURN, 064M  
Compressed Air (size, location) 1-1/2", 064M

**SEWERS:** Storm 12" Sanitary 8"

**METERS:**

Gas (size, location) N/A  
Water (size, location) 6", 064M  
Electric (location) 060M

**ALARM SYSTEMS:**

Fire Alarm YES Panel Location 060M  
Fire Pump YES Pump Location 064M  
Sprinklers NO Panel Location N/A  
Other Alarms SECURITY SYSTEMS

**ELEVATORS:**

Number 3 Type (passenger, freight) 2 PASSENGER, 1 FREIGHT  
Manufacturer OTIS Size 2 @ 51" X 80", 1 @ 95" X 65"

**EMERGENCY GENERATOR:** Size N/A Location N/A

**KEY BOX LOCATION:** INSIDE EAST DOOR ON NORTH SIDE OF BUILDING

**ASBESTOS SURVEY (1986):**

LIMITED TO PIPE INSULATION IN THE MECHANICAL ROOMS AND CONDENSATE TANK INSULATION.

## BAKER SYSTEMS ENGINEERING BUILDING NARRATIVE

### HISTORY

Baker Systems Engineering Building construction was completed in 1968. Principal occupants include the Department of Industrial Systems Engineering and Academic Computing Services. The building was designed and built to house a computer center, offices, Industrial Engineering laboratories and classrooms. Its principle function has not changed since completion although the amount of space devoted to computing has increased. Facility use by category is: 39% data processing and computer centers, 28% office and office-related use, 17% mechanical/custodial/toilet, and 16% classroom or miscellaneous uses.

### PRIMARY SYSTEMS

The five-story structure is supported by concrete piers and caissons. Concrete footers support non-load-bearing walls. Cast-in-place concrete columns support concrete floors throughout. The exterior consists of concrete blocks with a brick, precast concrete and limestone veneer. The roof deck is structural concrete with a layer of tapered light-weight insulating concrete on it.

The building roof cover is original. There are a large number of blisters over the penthouse. There are also a number of blisters over the rest of the roof. The amount of equipment on the roof implies heavy foot traffic. While there have not been many reported roof leaks, the age, condition and foot traffic on this roofs warrants a roof replacement project. The project should be accomplished within the next five to ten years.

The exterior of the building has been recently cleaned, sealed and recaulked and is in good condition.

Most of the building glazing is fixed-pane. There are a small number of double-hung units on the north side of the first floor. While the windows are all single pane, the total surface area is limited.

### SECONDARY SYSTEMS

Interior partition walls are composed of concrete block or metal stud and drywall walls. Surface finishes are generally in good condition and consist primarily of paint on the concrete block and drywall. The interior of the stairwells requires repainting.

The primary floor covering in the building is vinyl tile. The restroom tile floors require cleaning but floors are generally in good condition otherwise. There have been several leaks in the penthouse. The floor in this area is not waterproof. The Department of Physical Facilities has a proposed project to install an elastomeric membrane with an epoxy surface to seal the floor in this area.

Ceilings are predominantly suspended acoustical tile. The restroom ceilings are drywalled. The ceiling in the building lobby on the first floor is dirty as are most of the diffusers and light fixtures in the first floor hallways. They require cleaning. The grids are beginning to yellow and it is particularly noticeable next to the extended hallway at the Dreese Lab addition. The hallway ceilings on the first and second floors should be cleaned and tiles replaced as needed. We are proposing a combined interior finishes maintenance project to clean and replace ceilings as needed on the first and second floors and paint the stairway walls from

the basement to the fifth floor. The ceilings are generally in better condition on the higher floors.

## SERVICE SYSTEMS

The building has two passenger elevators and one freight elevator. All three elevators are well utilized with the two passenger elevators being highly utilized. The interiors are in poor condition, there have been a large number of complaints about elevator service and the cars do not meet present code for communications and safety. The Department of Physical Facilities has proposed a project to upgrade and modernize all three elevators.

Most of the building is heated and cooled by a dual duct high velocity system. Air flow was reduced in the late 70's and several interior areas were converted to a variable air volume system. One of the original nine air handlers has been removed and another air handler is no longer used. One of the two original steam absorption chillers was replaced in 1980 with an electric centrifugal chiller to reduce operating costs. The remaining absorption chiller is no longer used and has not been operated in several years according to maintenance personnel.

The heat load in the building has increased steadily since it was built as the number of computers has increased. As a result, a number of single zone direct expansion systems have been added to provide cooling for computer labs and operations rooms. Occupants and maintenance personnel reported interior spaces are often stuffy and hot, particularly classrooms on the second and third floors. Additional air volume and cooling is required in these areas. Maintenance personnel have commented that while air flow can be increased, there is not a large enough supply of chilled water in the building to handle the additional cooling load. The remaining absorption chiller should be replaced with another 175-ton centrifugal chiller or the building should be added to the central chilled water loop being planned for the College of Business Complex to increase cooling capacity.

The cooling towers were replaced in 1980. Building HVAC systems are controlled by a Direct Digital Control system. No problems were found with either system.

Heating hot water is supplied by four steam converters. Two steam converters in the basement supply heating hot water for a limited radiation system and unit heaters. The two in the penthouse supply the hot water coils in the air handlers.

Domestic hot water is supplied from the University power plant. Supply is adequate. There were no major plumbing problems identified in the maintenance workorder system. Plumbing fixtures are still serviceable throughout the facility although the surface finish on most of the faucets are worn.

## ELECTRICITY

The building is equipped with two 750 KVA transformers. Each has a primary voltage of 13,200. One has a secondary voltage of 240 volts and the other has secondary voltage of 208/120. The Physical Facilities Department's Utilities Division's records indicate that the transformers have been utilized at approximately 58% of capacity last summer. There is an abundant supply of electrical power available. There is adequate electrical capacity and ample spare circuit space in all panels. We did observe that most of the hallway breaker panels were dirty.

The building lighting system is predominantly 4-tube fluorescent fixtures which are clean and in good condition throughout most areas except the first floor lobby

area. There is an adequate supply and distribution of convenience outlets throughout the building.

#### SAFETY STANDARDS

The building is equipped with portable fire extinguishers and standpipes in all three stairways. Smoke detectors are located in the HVAC ductwork and under the raised floor in the computer room. The building has lighted exit signs and an emergency lighting system.

The entrance on the south side of the building is sloped to accommodate wheelchairs and has a door that is equipped with an electric opener for the handicapped. All floors are handicapped accessible from the elevator.

#### ASBESTOS

The Ohio Board of Regents Facilities Asbestos Inspection and Risk Assessment Program's report: Inventory of Friable Asbestos-Containing Materials in Buildings of the Ohio State University (Main and Branch Campuses) and Recommendations for Corrective Action by PEI Associates, September 1986, identifies asbestos containing materials in the pipe and condensate tank insulation located in maintenance rooms in the basement and penthouse.

#### BUILDING PERIMETER

There is a driveway for the overhead door located on the west side of the building. The east side of the building has a paver plaza that has just been installed and is in very good condition. The sidewalk accessing the west door to the building has several heaved panels that require attention. The asphalt sidewalks on the south side of the building are cracked and should be repaired. The entrances to the facility are well lighted and secure. The plant bed along the south side of the building requires more bedding material.

**Maintenance Projects (LESS THAN \$5000)**

1. Repair sidewalk leading to west entrance, fill holes in driveway.  
Workorder # 01-5063-008229-51
2. Seal asphalt walk at the south side of the building.  
Workorder # 01-5063-008228-51
3. Clean hallway electrical breaker panels throughout the building.  
Workorder # 01-5064-111267-65
4. Install light over the blackboard in rm 291.  
Workorder # 01-5064-111263-71
5. Clean/scrub tile floors in restrooms.  
Workorder # 01-5064-008225-40
6. Paint overhead door on the west side of the building.  
Workorder # 01-5064-111247-65
7. Repair restroom door at 315T.  
Workorder # 01-5064-111290-71

20 MAY 94

**BUILDING EVALUATION SUMMARY**

**I. BUILDING INFORMATION**

FAC # 280 FACILITY NAME: BAKER SYSTEMS ENGINEERING  
 DATE: 5/2/94 INSPECTOR: JAMES P. HERTENSTEIN  
 YEAR CONSTRUCTED: 1968  
 GROSS SQ FT: 114,888 NET SQ FT: 87,094  
 REPLACEMENT COST \$ 17,266,000 \*

**II. COMPONENT RATING**

| COMPONENT         | BUILDING COMPONENT PERCENTAGE OF TOTAL COST ** | BUILDING COMPONENT REPLACEMENT COST | CONDITION VALUE MULTIPLIER FOR BLDG. COMPONENT | BUILDING COMPONENT CURRENT VALUE |
|-------------------|--|-------------------------------------|--|----------------------------------|
| Foundation        | 5.4  | 932,364                             | .91  | 848,451                          |
| Columns and Beams | 20.8   | 3,591,328                           | .92  | 3,304,022                        |
| Exterior Walls    | 10.4   | 1,795,664                           | .88  | 1,580,184                        |
| Windows & Doors   | 2.4  | 414,384                             | .82  | 339,795                          |
| Roofing           | 1.3  | 224,458                             | .61  | 136,919                          |
| Partitions & Drs. | 7.1  | 1,225,886                           | .86  | 1,054,262                        |
| Wall Finishes     | 2.7  | 466,182                             | .79  | 368,284                          |
| Floor Finishes    | 5.2  | 897,832                             | .82  | 736,222                          |
| Ceilings & Finish | 7.4  | 1,277,684                           | .72  | 919,932                          |
| Conveying         | 1.7  | 293,522                             | .65  | 190,789                          |
| Plumbing          | 2.3  | 397,118                             | .79  | 313,723                          |
| Heating           | 9.1  | 1,571,206                           | .83  | 1,304,101                        |
| Cooling & Vent.   | 9.7  | 1,674,802                           | .72  | 1,205,857                        |
| Elec. Ser. & Dist | 1.8  | 310,788                             | .98  | 304,572                          |
| Lighting & Power  | 12.1   | 2,089,186                           | .78  | 1,629,565                        |
| Safety Standards  | .6   | 103,596                             | .70  | 72,517                           |
| TOTALS            | 100.00   | 17,266,000                          |  | 14,309,195                       |

**III. BUILDING RATING SUMMARY**

**Overall Building Rating = 83%**

\* Replacement Cost assigned September 1991 by The Office of Campus Planning and Space Utilization without the furnishings and fixed equipment allocation.

\*\* Percent allocation of each building component is calculated from The Means Standard Construction Cost data for College Classroom Buildings.

**FOUNDATIONS**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

**A. SYSTEM DESCRIPTION**

|  | <u>N/A</u> | <u>Sat</u> | <u>Att</u> |
|--|------------|------------|------------|
| <b>a. Footings:</b>  |            |            |            |
| Individual Footings & Piers _____                                | [X]        | [ ]        | [ ]        |
| Continuous Footings <u>LOCATED UNDER WALLS AT THE PERIMETER</u>  | [ ]        | [X]        | [ ]        |
| Grade Beams _____  | [X]        | [ ]        | [ ]        |
| Piles _____  | [X]        | [ ]        | [ ]        |
| Caissons <u>UNDER ALL BUILDING COLUMNS</u>                       | [ ]        | [X]        | [ ]        |
| <br><b>b. Foundation Wall Materials:</b>                         |            |            |            |
| Steel _____  | [X]        | [ ]        | [ ]        |
| Concrete Cast-in-place _____                                     | [ ]        | [X]        | [ ]        |
| Concrete Block _____   | [X]        | [ ]        | [ ]        |
| Other _____  | [X]        | [ ]        | [ ]        |
| <br><b>c. Waterproofing and Underdrain:</b>                      |            |            |            |
| Coating _____  | [X]        | [ ]        | [ ]        |
| Membrane <u>EXTERIOR OF FOUNDATION WALLS AND UNDER THE SLAB</u>  | [ ]        | [X]        | [ ]        |
| Board 'CELOTEX' ON THE EXTERIOR OF THE FOUNDATION WALLS          | [ ]        | [X]        | [ ]        |
| Drain Tile <u>4" TILE AT THE PERIMETER AND UNDER THE SLAB</u>    | [ ]        | [X]        | [ ]        |
| <br><b>d. Slab on Grade (floor):</b>                             |            |            |            |
| Plain _____  | [X]        | [ ]        | [ ]        |
| Reinforced <u>6" SLAB THICKENED TO 10" UNDER PARTITION WALLS</u> | [ ]        | [X]        | [ ]        |
| <br><b>e. Special Substructures:</b>                             |            |            |            |
| _____  | [X]        | [ ]        | [ ]        |

**B. COMMENTS:**

NO PROBLEMS OBSERVED.

**C. COMPONENT RATING:**    (\$932,400 ) X ( 91 % ) = \$ 848,500  
    Possible                      Condition                      Component  
    Value                      Value Multiplier                      Value

**COLUMNS AND BEAMS**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

**A. SYSTEM DESCRIPTION**

**a. Columns and Beams:**

|  | N/A | Sat | Att |
|--|-----|-----|-----|
| Concrete-in-place THROUGHOUT             | [ ] | [X] | [ ] |
| Precast Concrete                         | [X] | [ ] | [ ] |
| Steel BAR JOISTS AT CEILING OF PENTHOUSE | [ ] | [X] | [ ] |
| Steel Fireproofing                       | [X] | [ ] | [ ] |
| Wood                                     | [X] | [ ] | [ ] |
| Other                                    | [X] | [ ] | [ ] |

**b. Floors:**

|                            |     |     |     |
|----------------------------|-----|-----|-----|
| Concrete Slab 5-3/4" THICK | [ ] | [X] | [ ] |
| Precast Slab               | [X] | [ ] | [ ] |
| Metal Deck                 | [X] | [ ] | [ ] |
| Metal Deck w/concrete fill | [X] | [ ] | [ ] |
| Wood                       | [X] | [ ] | [ ] |
| Other                      | [X] | [ ] | [ ] |

**c. Roof System:**

|                            |     |     |     |
|----------------------------|-----|-----|-----|
| Flat                       | [ ] | [X] | [ ] |
| Pitched                    | [X] | [ ] | [ ] |
| Concrete ABOVE FIFTH FLOOR | [ ] | [X] | [ ] |
| Steel DECK ABOVE PENTHOUSE | [ ] | [X] | [ ] |
| Wood                       | [X] | [ ] | [ ] |
| Other                      | [X] | [ ] | [ ] |

**B. COMMENTS:**

NO DEFLECTION OR OTHER STRUCTURAL PROBLEMS OBSERVED.

**C. COMPONENT RATING: (\$3,591,000) x ( 92 %) = \$3,304,000**

|          |                  |           |
|----------|------------------|-----------|
| Possible | Condition        | Component |
| Value    | Value Multiplier | Value     |

**EXTERIOR WALLS**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

**A. SYSTEM DESCRIPTION**

**a. Walls:**

|   | <u>N/A</u> | <u>Sat</u> | <u>Att</u> |
|---|------------|------------|------------|
| Concrete <u>EXPOSED FOUNDATION ON WEST SIDE</u>           | [ ]        | [X]        | [ ]        |
| Masonry <u>BRICK AND LIMESTONE</u>                        | [ ]        | [X]        | [ ]        |
| Metal Siding _____  | [X]        | [ ]        | [ ]        |
| Wood Siding _____   | [X]        | [ ]        | [ ]        |
| Other <u>PRECAST CONCRETE AND POLISHED GRANITE PANELS</u> | [ ]        | [X]        | [ ]        |

**b. Finishes:**

|              |     |     |     |
|--------------|-----|-----|-----|
| Stucco _____ | [X] | [ ] | [ ] |
| Paint _____  | [X] | [ ] | [ ] |
| Other _____  | [X] | [ ] | [ ] |

**B. COMMENTS:**

THE MASONRY WAS CLEANED AND SEALED IN 1991. THE CAULKING WAS ALSO REPLACED THE EXTERIOR IS IN GOOD CONDITION.

**C. COMPONENT RATING:**    (\$1,796,000) X ( 88 %) = \$1,580,000  
   Possible                      Condition                      Component  
   Value                      Value Multiplier                      Value

**EXTERIOR WINDOWS & DOORS**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

**A. SYSTEM DESCRIPTION**

| <b>a. Windows type &amp; number:</b>                         | <u>N/A</u> | <u>Sat</u> | <u>Att</u> |
|--|------------|------------|------------|
| Wood _____   | [X]        | [ ]        | [ ]        |
| Steel _____  | [X]        | [ ]        | [ ]        |
| Alum <u>147 FIXED UNITS, 12 SINGLE-HUNG UNITS</u>            | [ ]        | [X]        | [ ]        |
| Other <u>236 TINTED-GLASS SPANDREL PANELS</u>                | [ ]        | [X]        | [ ]        |
| <br>   |            |            |            |
| <b>b. Window glazing:</b>                                    |            |            |            |
| Single pane _____  | [ ]        | [X]        | [ ]        |
| Double pane _____  | [X]        | [ ]        | [ ]        |
| Other _____  | [X]        | [ ]        | [ ]        |
| <br>   |            |            |            |
| <b>c. Doors type &amp; number:</b>                           |            |            |            |
| Wood _____   | [X]        | [ ]        | [ ]        |
| Steel <u>3 SINGLE, OVERHEAD DOOR AT BASEMENT NEEDS PAINT</u> | [ ]        | [ ]        | [X]        |
| Alum <u>2 DOUBLE AND ONE SINGLE</u>                          | [ ]        | [X]        | [ ]        |
| Other _____  | [X]        | [ ]        | [ ]        |
| <br>   |            |            |            |
| <b>d. Shading Devices:</b>                                   |            |            |            |
| Types <u>VENETIAN BLINDS</u>                                 | [ ]        | [X]        | [ ]        |

**B. COMMENTS:**

NO PROBLEMS OBSERVED WITH THE WINDOWS. EXTERIOR GLAZING IS LIMITED.

**C. COMPONENT RATING:**    (\$414,400 ) X ( 82 % ) = \$339,800  
                                     Possible                      Condition                      Component  
                                     Value                      Value Multiplier                      Value

**ROOFING**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

**A. SYSTEM DESCRIPTION**

|   | N/A | Sat | Att |
|---|-----|-----|-----|
| <b>a. Roof Covering:</b>                      |     |     |     |
| Built-up _____                                | [X] | [ ] | [ ] |
| Built-up w/gravel 17,300 SF INSTALLED IN 1968 | [ ] | [ ] | [X] |
| Asphalt Shingle _____                         | [X] | [ ] | [ ] |
| Copper _____                                  | [X] | [ ] | [ ] |
| Glass (Skylight) _____                        | [X] | [ ] | [ ] |
| Slate _____                                   | [X] | [ ] | [ ] |
| Spanish Tile _____                            | [X] | [ ] | [ ] |
| Metal _____                                   | [X] | [ ] | [ ] |
| Other _____                                   | [X] | [ ] | [ ] |

**c. Flashing:**

|  |     |     |     |
|--|-----|-----|-----|
| Base & Counter BITUMEN-COATED FELT AND STAINLESS STEEL | [ ] | [X] | [ ] |
| Cap STAINLESS STEEL AT PARAPETS                        | [ ] | [X] | [ ] |
| Through Wall _____                                     | [X] | [ ] | [ ] |
| Valley & Ridge _____                                   | [X] | [ ] | [ ] |

**d. Gravel Stop & Edge Strips:**

|                            |     |     |     |
|----------------------------|-----|-----|-----|
| Type STAINLESS STEEL _____ | [ ] | [X] | [ ] |
|----------------------------|-----|-----|-----|

**e. Drainage:**

|   |     |     |     |
|---|-----|-----|-----|
| Gutters w/ Exterior Downspouts _____          | [X] | [ ] | [ ] |
| Scuppers w/ Exterior Downspouts NO DOWNSPOUTS | [ ] | [X] | [ ] |
| Drains w/ Interior Storm Drains _____         | [ ] | [X] | [ ] |

**f. Parapets:**

|                           |     |     |     |
|---------------------------|-----|-----|-----|
| Concrete _____            | [X] | [ ] | [ ] |
| Brick _____               | [X] | [ ] | [ ] |
| Block _____               | [X] | [ ] | [ ] |
| Precast _____             | [X] | [ ] | [ ] |
| Other LIMESTONE AND BLOCK | [ ] | [X] | [ ] |

**g. Insulation:**

|   |     |     |     |
|---|-----|-----|-----|
| Type TAPERED LIGHT-WEIGHT CONCRETE AND 1-1/2" RIGID | [ ] | [X] | [ ] |
|---|-----|-----|-----|

**B. COMMENTS**

THERE ARE A LARGE NUMBER OF BLISTERS OVER THE PENTHOUSE. THERE ARE ALSO A SMALLER NUMBER OF BLISTERS OVER THE REST OF THE ROOF. THE AMOUNT OF EQUIPMENT ON THE ROOF IMPLIES HEAVY FOOT TRAFFIC. WHILE THERE HAVE NOT BEEN MANY REPORTED ROOF LEAKS, THE AGE, CONDITION AND FOOT TRAFFIC SUGGEST THAT A ROOF REPLACEMENT PROJECT SHOULD BE PLANNED TO BE ACCOMPLISHED IN THE NEXT FIVE TO TEN YEARS.

**C. COMPONENT RATING:**    (\$224,500 ) X ( 61 % ) = \$136,900

|          |                  |           |
|----------|------------------|-----------|
| Possible | Condition        | Component |
| Value    | Value Multiplier | Value     |

**PARTITIONS & DOORS**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

**A. SYSTEM DESCRIPTION**

| <b>a. Partition Framing:</b>                                    | N/A | Sat | Att |
|---|-----|-----|-----|
| Concrete Block <u>PREDOMINANT</u>                               | [ ] | [X] | [ ] |
| Glazed Block <u>LIMITED USE - RESTROOMS</u>                     | [ ] | [X] | [ ] |
| Wood Stud _____   | [X] | [ ] | [ ] |
| Metal Stud <u>SOME OFFICE AND CLASSROOM WALLS</u>               | [ ] | [X] | [ ] |
| Structural Tile _____   | [X] | [ ] | [ ] |
| Rated _____   | [X] | [ ] | [ ] |
| Other <u>CAST-IN-PLACE CONCRETE, PRE-FORMED METAL, BRICK</u>    | [ ] | [X] | [ ] |
| <b>b. Special partitions and Walls:</b>                         |     |     |     |
| Toilet <u>METAL</u>   | [ ] | [X] | [ ] |
| Screen Walls _____  | [X] | [ ] | [ ] |
| Gate _____  | [X] | [ ] | [ ] |
| Other <u>FOLDING ACCORDION-TYPE PARTITIONS IN SOME ROOMS</u>    | [ ] | [X] | [ ] |
| <b>c. Wall Material:</b>  |     |     |     |
| Plaster _____   | [X] | [ ] | [ ] |
| Plaster Board <u>USED WITH METAL STUDS</u>                      | [ ] | [X] | [ ] |
| Glass <u>GLAZING IN SOME WALLS AT DEPARTMENTAL SPACE</u>        | [ ] | [X] | [ ] |
| Plywood _____   | [X] | [ ] | [ ] |
| Paneling _____  | [X] | [ ] | [ ] |
| Trim & Wainscot _____   | [X] | [ ] | [ ] |
| Tile/Glazed <u>RESTROOMS</u>                                    | [ ] | [X] | [ ] |
| Other <u>METAL</u>  | [ ] | [X] | [ ] |
| <b>d. Interior Doors &amp; Frames:</b>                          |     |     |     |
| Met Door/Met Frame <u>MAINTENANCE AND FIRE DOORS AT STAIRS</u>  | [ ] | [ ] | [X] |
| Wood Door/Wood Frame _____                                      | [X] | [ ] | [ ] |
| Wood Door/Metal Frame <u>PREDOMINANT</u>                        | [ ] | [ ] | [X] |
| Glazing <u>AT STAIRWAY DOORS</u>                                | [ ] | [X] | [ ] |
| Rollup _____  | [X] | [ ] | [ ] |
| Sliding <u>SEVERAL METAL DOORS AT THE BASEMENT LABORATORIES</u> | [ ] | [X] | [ ] |
| Other _____   | [X] | [ ] | [ ] |
| <b>e. Hardware:</b>   |     |     |     |
| Door Closers _____  | [ ] | [X] | [ ] |
| Lock Sets _____   | [ ] | [X] | [ ] |
| Kick/Push Plates _____  | [ ] | [X] | [ ] |
| Thresholds _____  | [ ] | [X] | [ ] |
| Panic Devices _____   | [ ] | [X] | [ ] |
| Security & Detection _____                                      | [ ] | [X] | [ ] |
| Automatic Openers <u>HANDICAPPED ENTRANCE DOORS</u>             | [ ] | [X] | [ ] |
| Other _____   | [X] | [ ] | [ ] |

**B. COMMENTS:**

THE METAL FIRE DOORS AT THE STAIRWAYS SHOULD BE PAINTED. THE NORTH DOORS AT THE MAIN LOBBY HAVE BEEN REPAIRED SEVERAL TIMES. THE DOOR TO 315T HAS A SPRUNG HINGE AND WILL NOT CLOSE COMPLETELY. NO STRUCTURAL DEFECTS WERE OBSERVED WITH THE PARTITIONS.

**C. COMPONENT RATING:**    (\$1,226,000) x ( 86 %) = \$1,054,000

|          |                  |           |
|----------|------------------|-----------|
| Possible | Condition        | Component |
| Value    | Value Multiplier | Value     |

**WALL FINISHES**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

| <b>A. SYSTEM DESCRIPTION</b>       | <u>N/A</u> | <u>Sat</u> | <u>Att</u> |
|------------------------------------|------------|------------|------------|
| a. Paint <u>PREDOMINANT FINISH</u> | [ ]        | [ ]        | [X]        |
| b. Wall Coating _____              | [X]        | [ ]        | [ ]        |
| c. Wall Coverings _____            | [X]        | [ ]        | [ ]        |
| d. Paneling                        |            |            |            |
| Prefinished                        | [X]        | [ ]        | [ ]        |
| Plank                              | [X]        | [ ]        | [ ]        |
| e. Cork _____                      | [X]        | [ ]        | [ ]        |
| f. Wallpaper _____                 | [X]        | [ ]        | [ ]        |
| g. Ceramic Tile <u>RESTROOMS</u>   | [ ]        | [ ]        | [X]        |
| h. Trim & Wainscot _____           | [X]        | [ ]        | [ ]        |
| i. Decoration _____                | [X]        | [ ]        | [ ]        |
| j. Glass <u>LIMITED USE</u>        | [ ]        | [X]        | [ ]        |
| k. Other _____                     | [ ]        | [X]        | [ ]        |

**B. COMMENTS**

THE PAINT IN THE STAIRWAYS PRIMARILY UP TO THE FOURTH FLOOR IS IN POOR CONDITION.  
THE BASE COURSE OF CERAMIC TILE IN THE RESTROOMS IS VERY DIRTY.

**C. COMPONENT RATING:**    (\$466,200 ) X ( 79 %) = \$410,200  
                                     Possible            Condition            Component  
                                     Value            Value Multiplier    Value

**FLOOR FINISHES**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

**A. SYSTEM DESCRIPTION**

|   | N/A | Sat | Att |
|---|-----|-----|-----|
| <b>a. Carpet:</b>   |     |     |     |
| Rolled DEPARTMENTAL SPACE _____                                     | [ ] | [X] | [ ] |
| Tile _____  | [X] | [ ] | [ ] |
| <b>b. Composition:</b>  |     |     |     |
| Epoxy _____   | [X] | [ ] | [ ] |
| Synthetic _____   | [X] | [ ] | [ ] |
| Other _____   | [X] | [ ] | [ ] |
| <b>c. Concrete Topping:</b>   |     |     |     |
| Clear Sealant MAINTENANCE ROOMS _____                               | [ ] | [ ] | [X] |
| Abrasive _____  | [X] | [ ] | [ ] |
| Epoxy _____   | [X] | [ ] | [ ] |
| Aggregate _____   | [X] | [ ] | [ ] |
| <b>d. Resilient:</b>  |     |     |     |
| Vinyl Tile PREDOMINANT - GOOD CONDITION _____                       | [ ] | [X] | [ ] |
| Linoleum _____  | [X] | [ ] | [ ] |
| Vinyl _____   | [X] | [ ] | [ ] |
| Rubber _____  | [X] | [ ] | [ ] |
| Cork _____  | [X] | [ ] | [ ] |
| <b>e. Ceramic Tile</b> RESTROOMS - NEEDS A THOROUGH SCRUBBING _____ | [ ] | [ ] | [X] |
| <b>f. Masonry</b> _____   | [X] | [ ] | [ ] |
| <b>g. Terrazzo</b> _____  | [X] | [ ] | [ ] |
| <b>h. Wood</b> _____  | [X] | [ ] | [ ] |
| <b>i. Metal</b> _____   | [X] | [ ] | [ ] |

**B. COMMENTS**

VINYL TILE IS IN GOOD CONDITION. THE DEPARTMENT OF PHYSICAL FACILITIES HAS PROPOSED A PROJECT TO INSTALL A WATER PROOF MEMBRANE UNDER THE COOLING TOWERS LOCATED IN THE PENTHOUSE IN PLACE OF THE CONCRETE SEALER. MAINTENANCE PERSONNEL COMMENTED THAT THE COOLING TOWERS USUALLY LEAK AT LEAST ONCE A YEAR AND THAT A WATERTIGHT FLOOR IS A NECESSITY IN THIS AREA.

**C. COMPONENT RATING:**    (\$897,800 ) X ( 82 %) = \$736,200  
    Possible                      Condition                      Component  
    Value                      Value Multiplier                      Value

**CEILING AND FINISHES**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

**A. SYSTEM DESCRIPTION**

| <b>a. System Type:</b>                                   | N/A | Sat | Att |
|--|-----|-----|-----|
| Exposed <u>MAINTENANCE ROOMS</u>                         | [ ] | [X] | [ ] |
| Applied to Structure <u>DRYWALL &amp; 12" X 12" TILE</u> | [ ] | [X] | [ ] |
| Suspended <u>PREDOMINANT</u>                             | [ ] | [ ] | [X] |

**b. Materials:**

|                           |     |     |     |
|---------------------------|-----|-----|-----|
| Drywall <u>RESTROOMS</u>  | [ ] | [X] | [ ] |
| Plaster _____             | [X] | [ ] | [ ] |
| Mineral Fiber Board _____ | [ ] | [ ] | [X] |
| Metal Pan _____           | [X] | [ ] | [ ] |
| Luminous Panels _____     | [X] | [ ] | [ ] |
| Other _____               | [X] | [ ] | [ ] |

**c. Finishes:**

|                   |     |     |     |
|-------------------|-----|-----|-----|
| Paint _____       | [X] | [ ] | [ ] |
| Fabric _____      | [X] | [ ] | [ ] |
| Prefinished _____ | [ ] | [ ] | [X] |
| Other _____       | [X] | [ ] | [ ] |

**d. Openings & Inserts:**

|   |     |     |     |
|---|-----|-----|-----|
| Air Distribution <u>DIRTY</u>                       | [ ] | [ ] | [X] |
| Lighting Fixtures <u>HALLWAY FIXTURES ARE DIRTY</u> | [ ] | [ ] | [X] |
| Access Panels _____                                 | [ ] | [X] | [ ] |
| Skylights _____                                     | [X] | [ ] | [ ] |
| Fire Protection _____                               | [X] | [ ] | [ ] |
| Other _____   | [X] | [ ] | [ ] |

**B. COMMENTS:**

THE DIFFUSERS IN THE LOBBY AREA OF THE FIRST FLOOR ARE RUSTY AND DIRTY, THEY SHOULD BE CLEANED AND PAINTED. THE LIGHT FIXTURES IN THE FIRST FLOOR HALLWAYS ARE SOILED AND THERE IS A GREAT DEAL OF DIRT AT THE AIR DIFFUSERS THROUGHOUT THE FIRST FLOOR. THE GRIDS FOR THE SUSPENDED CEILING ARE BEGINNING TO YELLOW AND THIS IS PARTICULARLY EVIDENT AT THE JUNCTURE WITH THE NEW ADDITION TO DREESE LAB AT THE NORTH END OF THE FIRST AND SECOND FLOOR HALLWAYS.

**C. COMPONENT RATING:**    (\$1,278,000) x ( 72 %) = \$919,900  
    Possible                      Condition                      Component  
    Value                      Value Multiplier                      Value

**CONVEYING**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

**A. SYSTEM DESCRIPTION**

**a. Elevators:**

|   | N/A | Sat | Att |
|---|-----|-----|-----|
| Number <u>3</u>   | [ ] | [ ] | [X] |
| Type <u>2 PASSENGER @ SOUTH &amp; 1 FREIGHT @ NORTH, ALL OTIS</u> | [ ] | [X] | [ ] |
| Speed <u>200 FPM EACH</u>   | [ ] | [X] | [ ] |
| Capacity (lbs) <u>PASSENGER - 2500 EACH, FREIGHT - 4500</u>       | [ ] | [X] | [ ] |
| Dimensions <u>PASSENGER - 51" X 80", FREIGHT - 95" X 65"</u>      | [ ] | [X] | [ ] |
| Door Operation:   |     |     |     |
| Center PASSENGER ELEVATORS  | [ ] | [X] | [ ] |
| To Side FREIGHT ELEVATOR  | [ ] | [X] | [ ] |
| Handicapped-accessible controls _____                             | [ ] | [ ] | [X] |

**b. Lifts and Hoists:**

|              |     |     |     |
|--------------|-----|-----|-----|
| Number _____ | [X] | [ ] | [ ] |
| Type _____   | [X] | [ ] | [ ] |

**c. Moving Stairs and Walks:**

|              |     |     |     |
|--------------|-----|-----|-----|
| Number _____ | [X] | [ ] | [ ] |
| Type _____   | [X] | [ ] | [ ] |

**d. Conveyors:**

|              |     |     |     |
|--------------|-----|-----|-----|
| Number _____ | [X] | [ ] | [ ] |
| Type _____   | [X] | [ ] | [ ] |

**e. Pneumatic Tubes:**

|              |     |     |     |
|--------------|-----|-----|-----|
| Number _____ | [X] | [ ] | [ ] |
| Type _____   | [X] | [ ] | [ ] |

**B. COMMENTS:**

THE DEPARTMENT OF PHYSICAL FACILITIES HAS PROPOSED A PROJECT TO UPGRADE AND MODERNIZE THE THREE EXISTING ELEVATORS IN THE BUILDING. THEY HAVE NOT BEEN RENOVATED SINCE INSTALLATION AND THE PASSENGER ELEVATORS ARE SUBJECT TO A HIGH DEGREE OF UTILIZATION. THE INTERIORS ARE IN POOR CONDITION AND THE CONTROLS SHOULD BE MODERNIZED TO IMPROVE SERVICE AND PROVIDE FIRE FIGHTERS SERVICE. NEW DOOR OPERATION DEVICES ARE ALSO REQUIRED IN ADDITION TO FINISHES RENOVATION.

**C. COMPONENT RATING:**    (\$293,500 ) X ( 65 %) = \$190,800  
                                     Possible                      Condition                      Component  
                                     Value                      Value Multiplier                      Value

**MECHANICAL/PLUMBING**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

**A. SYSTEM DESCRIPTION**

| <b>a. Services Available:</b>                         | N/A | Sat | Att |
|---|-----|-----|-----|
| Cold Water 6" SUPPLY IN ROOM 064M                     | [ ] | [X] | [ ] |
| Hot Water 3" SUPPLY, 1-1/4" RETURN - ROOM 064M        | [ ] | [X] | [ ] |
| Acid Waste SMALL SYSTEM INSTALLED FOR ROOM 140 AREA   | [ ] | [X] | [ ] |
| Oxygen  | [X] | [ ] | [ ] |
| Natural Gas 2" - 064M                                 | [ ] | [X] | [ ] |
| Vacuum CENTRAL CLEANING SYSTEM NO LONGER USED         | [X] | [ ] | [ ] |
| Distilled Water                                       | [X] | [ ] | [ ] |
| Compressed Air 1-1/2" SUPPLY FROM POWER PLANT IN 064M | [ ] | [X] | [ ] |
| Other   | [X] | [ ] | [ ] |
| <b>b. Piping &amp; Fittings:</b>                      |     |     |     |
| Cast Iron WASTER LINES AND VENTS                      | [ ] | [X] | [ ] |
| Copper Tubing SOME DOMESTIC WATER AND COMPRESSED AIR  | [ ] | [X] | [ ] |
| Plastic   | [X] | [ ] | [ ] |
| Steel WATER AND STEAM LINES                           | [ ] | [X] | [ ] |
| Glass   | [X] | [ ] | [ ] |
| Other   | [X] | [ ] | [ ] |
| <b>c. Water Heaters:</b>                              |     |     |     |
| Electric  | [X] | [ ] | [ ] |
| Gas   | [X] | [ ] | [ ] |
| Oil   | [X] | [ ] | [ ] |
| Steam Converter                                       | [X] | [ ] | [ ] |
| Other SUPPLIED FROM THE UNIVERSITY POWER PLANT        | [ ] | [X] | [ ] |
| <b>d. Drainage:</b>                                   |     |     |     |
| Storm Drains  | [ ] | [X] | [ ] |
| Sanitary Drainage                                     | [ ] | [X] | [ ] |
| Combined Storm/San.                                   | [X] | [ ] | [ ] |
| Floor Drains RESTROOMS AND LABS                       | [ ] | [X] | [ ] |
| <b>e. Fixtures:</b>                                   |     |     |     |
| Water Closets        26                               | [ ] | [X] | [ ] |
| Urinals              19                               | [ ] | [X] | [ ] |
| Lavatories 22 + 2 WASH FOUNTAINS                      | [ ] | [X] | [ ] |
| Showers   | [X] | [ ] | [ ] |
| Kitchen Sinks        3                                | [ ] | [X] | [ ] |
| Service Sinks        6                                | [ ] | [X] | [ ] |
| Drinking Fountains                                    | [X] | [ ] | [ ] |
| Electric Water Coolers                                | [ ] | [X] | [ ] |
| <b>f. Sprinkler Systems:</b>                          |     |     |     |
| Wet   | [X] | [ ] | [ ] |
| Dry   | [X] | [ ] | [ ] |
| <b>g. Standpipe Systems:</b>                          |     |     |     |
| Wet 3 - 6" PIPES - ONE AT EACH STAIRWAY               | [ ] | [X] | [ ] |
| Dry   | [X] | [ ] | [ ] |
| Valves LOCATED AT EACH STAIRWAY LANDING               | [ ] | [X] | [ ] |
| Hose Cabinets ADJACENT TO STAIRWAY DOORS - EACH FLOOR | [ ] | [X] | [ ] |

**B. COMMENTS:**

MAINTENANCE PERSONNEL DID NOT IDENTIFY ANY EXISTING PROBLEMS.

**C. COMPONENT RATING: (\$397,100 ) X ( 79 %) = \$313,700**

|          |                  |           |
|----------|------------------|-----------|
| Possible | Condition        | Component |
| Value    | Value Multiplier | Value     |

**MECHANICAL/HEATING**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

**A. SYSTEM DESCRIPTION**

| <b>a. Heat Source:</b>  | N/A | Sat | Att |
|---|-----|-----|-----|
| Central Plant Steam <u>4" SUPPLY, 3" COND. RETURN - RM 064M</u> | [ ] | [X] | [ ] |
| Central Plant Hot Water _____                                   | [X] | [ ] | [ ] |
| Boilers: Type _____   | [X] | [ ] | [ ] |
| Size _____  | [X] | [ ] | [ ] |
| Furnace: Type _____   | [X] | [ ] | [ ] |
| Size _____  | [X] | [ ] | [ ] |
| Heat Pump: Type _____   | [X] | [ ] | [ ] |
| Size _____  | [X] | [ ] | [ ] |

| <b>b. System Type:</b>                                    | [X] | [ ] | [ ] |
|---|-----|-----|-----|
| Steam _____   | [X] | [ ] | [ ] |
| Hot Water <u>LIMITED FORCED HOT WATER SYSTEM</u>          | [ ] | [X] | [ ] |
| Air <u>PREDOMINANT SYSTEM - AIR HANDLER COILS</u>         | [ ] | [X] | [ ] |
| Multizone _____   | [X] | [ ] | [ ] |
| Dual Duct <u>PRIMARY SYSTEM IN THE BUILDING</u>           | [ ] | [X] | [ ] |
| Terminal Reheat <u>LIMITED USE</u>                        | [ ] | [X] | [ ] |
| Variable Volume <u>SOME INTERIOR SPACES WERE MODIFIED</u> | [ ] | [X] | [ ] |
| Other _____   | [X] | [ ] | [ ] |

| <b>c. Space Equipment:</b>                                     | [ ] | [X] | [ ] |
|--|-----|-----|-----|
| Radiators <u>FIN-TUBE RADIATION BELOW WINDOWS AT 1ST FLOOR</u> | [ ] | [X] | [ ] |
| Convectors _____   | [X] | [ ] | [ ] |
| 2-Pipe Fan Coil _____  | [X] | [ ] | [ ] |
| Unit Heaters <u>MECHANICAL ROOMS AND ENTRANCES</u>             | [ ] | [X] | [ ] |
| Other _____  | [X] | [ ] | [ ] |

| <b>d. Control Type:</b> | [ ] | [X] | [ ] |
|-------------------------|-----|-----|-----|
| Pneu _____              | [ ] | [X] | [ ] |
| Electric _____          | [X] | [ ] | [ ] |
| DDC _____               | [ ] | [X] | [ ] |
| Manual Valves _____     | [X] | [ ] | [ ] |

**B. COMMENTS:**

HEATING HOT WATER IS PROVIDED FOR THE RADIATION SYSTEM FROM TWO STEAM CONVERTERS LOCATED IN THE BASEMENT MECHANICAL ROOM. HEATING HOT WATER IS PROVIDED FOR THE AIR HANDLERS FROM TWO STEAM CONVERTERS LOCATED IN PENTHOUSE. THE SYSTEM IS FUNCTIONING ADEQUATELY AT THIS TIME.

**C. COMPONENT RATING:**    (\$1,571,000) X ( 83 %) = \$1,304,000  
                                     Possible                      Condition                      Component  
                                     Value                      Value Multiplier                      Value

**COOLING & VENTILATING**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

**A. SYSTEM DESCRIPTION**

|   | N/A | Sat | Att |
|---|-----|-----|-----|
| <b>a. System:</b>   |     |     |     |
| Type <u>DDHV, MODIFIED VAV AND SEVERAL SINGLE-ZONE DX SYS.</u>      | [ ] | [ ] | [X] |
| Capacity <u>APPROXIMATELY 250 TONS + 173 TONS ABSORPTION</u>        | [ ] | [ ] | [X] |
| <b>b. Chillers:</b>   |     |     |     |
| Centrifugal <u>TRANE, 175 TONS CAPACITY, INSTALLED 1980</u>         | [ ] | [X] | [ ] |
| Reciprocating _____   | [X] | [ ] | [ ] |
| Absorption <u>TRANE, 173 TONS CAPACITY, INSTALLED 1968</u>          | [ ] | [ ] | [X] |
| <b>c. Cooling Towers:</b>   |     |     |     |
| Type <u>2 MARLEYS</u>   | [ ] | [X] | [ ] |
| Capacity <u>469 TONS TOTAL CAPACITY</u>                             | [ ] | [X] | [ ] |
| <b>d. Condensers:</b> <u>5 AIR COOLED CONDENSERS FOR DX SYSTEMS</u> | [ ] | [X] | [ ] |
| <b>e. Space Equipment:</b>  |     |     |     |
| Direct Expansion -  |     |     |     |
| Window units _____  | [X] | [ ] | [ ] |
| Thru-the-wall _____   | [X] | [ ] | [ ] |
| Single zone <u>USED EXTENSIVELY TO AUGMENT COOLING</u>              | [ ] | [X] | [ ] |
| Single zone con. vol. _____   | [X] | [ ] | [ ] |
| Other _____   | [X] | [ ] | [ ] |
| Air/Water -   |     |     |     |
| 2-pipe fan coil _____   | [X] | [ ] | [ ] |
| Unit ventilators _____  | [X] | [ ] | [ ] |
| Terminal reheat <u>REMOVED TO CONSERVE ENERGY</u>                   | [X] | [ ] | [ ] |
| Variable volume <u>SOME INTERIOR SPACES WERE MODIFIED</u>           | [ ] | [X] | [ ] |
| Dual Duct <u>PRIMARY SYSTEM</u>                                     | [ ] | [X] | [ ] |
| <b>f. Special Systems:</b>  |     |     |     |
| Type _____  | [X] | [ ] | [ ] |
| Capacity _____  | [X] | [ ] | [ ] |
| <b>g. Control Systems:</b>  |     |     |     |
| Pneu <u>ACTUATORS</u>   | [ ] | [X] | [ ] |
| Electric _____  | [X] | [ ] | [ ] |
| Electronic <u>CSI-7700 DIRECT DIGITAL CONTROL SYSTEM</u>            | [ ] | [X] | [ ] |
| <b>h. Fans:</b>   |     |     |     |
| Exhaust <u>6</u>  | [ ] | [X] | [ ] |
| Recirculating <u>7 OF 9 ORIGINAL AIR HANDLERS STILL IN USE</u>      | [ ] | [ ] | [X] |

**B. COMMENTS:**

AIR VOLUME WAS REDUCED TO CONSERVE ENERGY IN THE 1970'S. THE ABSORPTION CHILLER IS NO LONGER FUNCTIONAL WHICH HAS REDUCED THE AVAILABLE CHILLED WATER SUPPLY IN THE BUILDING. THE INCREASING HEAT LOAD RESULTING FROM ADDITIONAL COMPUTERS HAS OVERCOME THE CURRENT SYSTEMS ABILITY TO ADEQUATELY COOL THE BUILDING. AIR FLOW SHOULD BE INCREASED IN THE BUILDING AFTER ADDITIONAL CHILLED WATER IS MADE AVAILABLE EITHER THROUGH THE INSTALLATION OF REPLACEMENT CHILLER OR FROM AN EXTERNAL SOURCE.

**C. COMPONENT RATING:**    (\$1,675,000) x ( 72 % ) = \$ 1,206,000

|          |                  |           |
|----------|------------------|-----------|
| Possible | Condition        | Component |
| Value    | Value Multiplier | Value     |

ELECTRICAL/SERVICE & DISTRIBUTION

FAC #280 DATE 5/2/94 INSPECTOR: JPH

A. SYSTEM DESCRIPTION

(a)Service:

Substation MCCRACKEN - CIRCUIT (PGN5/PGS5)

Primary Voltage 13,200 VOLTS

Transformer:

| Manufacture      | Type | KVA | Secondary Voltages |
|------------------|------|-----|--------------------|
| GENERAL ELECTRIC | OIL  | 750 | 240 DELTA          |
| GENERAL ELECTRIC | OIL  | 750 | 208/120            |

(b)Distribution System:

Panelboard (type) CIRCUIT BREAKERS

Voltage 120/208

Amperage 4400 AMPS

Conduit ALUMINUM AND GALVANIZED STEEL

Conductor COPPER

Wire (type) VARIES

Armored Cable LIMITED USE

Other N/A

(c)Emergency System:

General or (type & capacity) N/A

B. COMMENTS:

THE TWO BUILDING TRANSFORMERS WERE REPLACED IN 1990 IN THE PCB REPLACEMENT PROJECT. PHYSICAL FACILITIES RECORDS INDICATE THAT THE TRANSFORMERS ARE UTILIZED AT APPROXIMATELY 58% OF CAPACITY.

C. COMPONENT RATING: (\$310,800 ) x ( 98 % ) = \$304,600

|          |                  |           |
|----------|------------------|-----------|
| Possible | Condition        | Component |
| Value    | Value Multiplier | Value     |

**ELECTRICAL/LIGHTING & POWER**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

**A. SYSTEM DESCRIPTION**

**a. Lighting (lamp type):**

|  | N/A | Sat | Att |
|--|-----|-----|-----|
| Fluor <u>FIXTURES ARE DIRTY IN LOWER FLOOR HALLS</u>           | [ ] | [ ] | [X] |
| Incand <u>VARIABLE INTENSITY SPOT LIGHTS, MECHANICAL ROOMS</u> | [ ] | [X] | [ ] |
| HID _____  | [ ] | [X] | [ ] |
| Other _____  | [X] | [ ] | [ ] |

**b. Receptacles & Switches:**

|   |     |     |     |
|---|-----|-----|-----|
| Type & Capacity <u>GROUND 120 VOLT DUPLEX</u> | [ ] | [X] | [ ] |
|---|-----|-----|-----|

**c. Special:**

|                             |     |     |     |
|-----------------------------|-----|-----|-----|
| Baseboard Heat _____        | [X] | [ ] | [ ] |
| Lightning Protection _____  | [ ] | [X] | [ ] |
| Communication & Alarm _____ | [ ] | [X] | [ ] |
| Data Systems _____          | [ ] | [X] | [ ] |

**B. COMMENTS:**

THE ELECTRICAL DISTRIBUTION BREAKER BOXES THROUGHOUT THIS BUILDING ARE DIRTY. NO PROBLEMS WERE IDENTIFIED BY MAINTENANCE PERSONNEL OR OCCUPANTS.

C. COMPONENT RATING:    (\$2,089,000 ) X ( 78 % ) = \$1,630,000  
                                  Possible                      Condition                      Component  
                                  Value                      Value Multiplier                      Value

**SAFETY STANDARDS**

FAC #280      DATE 5/2/94      INSPECTOR: JPH

N/A      Sat      Att

**(a) Exits:**

Stair Construction:  
 concrete \_\_\_\_\_  [ ] [ ]  
 steel WITH CONCRETE PANS \_\_\_\_\_  [ ] [ ]  
 wood \_\_\_\_\_  [ ] [ ]  
 Number of exits 3 \_\_\_\_\_  [ ] [ ]

**(b) Fire Rating:**

Construction Type: I  II \_\_\_\_\_ III \_\_\_\_\_ IV \_\_\_\_\_ V \_\_\_\_\_ VI \_\_\_\_\_  
 Building Height: 68 \_\_\_\_\_ ft., 5 \_\_\_\_\_ stories

**(c) Extinguishing Systems:**

Portable WATER, CO-2 AND ABC THROUGHOUT \_\_\_\_\_  [ ] [ ]  
 Standpipe 3 - 6" LOCATED AT STAIRWAYS \_\_\_\_\_  [ ] [ ]  
 Hose Cabinets LOCATED ADJACENT TO THE STAIRWAYS \_\_\_\_\_  [ ] [ ]  
 Sprinklers \_\_\_\_\_  [ ] [ ]  
 Suppression HALON SYSTEM IN SOME AREAS \_\_\_\_\_  [ ] [ ]  
 Other \_\_\_\_\_  [ ] [ ]

**(d) Detection & Alarm Systems:**

Manual Alarm \_\_\_\_\_  [ ] [ ]  
 Annunciator LOCATED IN 060M \_\_\_\_\_  [ ] [ ]  
 Smoke Detectors IN DUCTWORK AND RAISED FLOOR \_\_\_\_\_  [ ] [ ]

**(e) Lighting Systems:**

Exit Signs \_\_\_\_\_  [ ] [ ]  
 Exit Lighting \_\_\_\_\_  [ ] [ ]  
 Emergency Lighting \_\_\_\_\_  [ ] [ ]  
 Emergency Generator \_\_\_\_\_  [ ] [ ]

**B. COMMENTS:**  
NO PROBLEMS OBSERVED.

**C. COMPONENT RATING:**    (\$103,600 ) X ( 70 % ) = \$72,500  
                                  Possible      Condition      Component  
                                  Value      Value Multiplier      Value

**BUILDING PERIMETER EVALUATION**

FAC #280                      DATE 5/2/94                      INSPECTOR: JPH

**A. SYSTEM DESCRIPTION**

|  | N/A | Sat | Att |
|--|-----|-----|-----|
| 1. Building Access:  |     |     |     |
| Driveway <u>NORTH SIDE OF BLDG - ACCESS BASEMENT AREA</u>  | [ ] | [X] | [ ] |
| Loading Dock <u>NEW DOCK UNDER CONSTRUCTION FOR DREESE</u> | [X] | [ ] | [ ] |
| Sidewalks  |     |     |     |
| Front <u>PAVER STONE PLAZA</u>                             | [ ] | [X] | [ ] |
| Side <u>ASPHALT WALKS TO SOUTH ARE CRACKING</u>            | [ ] | [ ] | [X] |
| Rear <u>CONCRETE WALK NEXT TO DRIVE IS UNEVEN</u>          | [ ] | [ ] | [ ] |
| Steps  |     |     |     |
| Front <u>NORTH AND SOUTH ENTRANCES</u>                     | [ ] | [X] | [ ] |
| Side _____   | [X] | [ ] | [ ] |
| Rear _____   | [X] | [ ] | [ ] |
| Handicap Ramp <u>SIDEWALK SLOPES UP TO MAIN ENTRANCE</u>   | [X] | [ ] | [ ] |
| 2. Lawn and Landscaping:                                   |     |     |     |
| Lawn <u>POOR CONDITION AT CONSTRUCTION SITE</u>            | [ ] | [ ] | [X] |
| Shrubs <u>REQUIRE TRIMMING AT DRIVEWAY</u>                 | [ ] | [ ] | [X] |
| Trees _____  | [ ] | [X] | [ ] |
| Undesirable Insect _____                                   | [X] | [ ] | [ ] |
| Bedding Material <u>SOUTH BEDS REQUIRE MULCH</u>           | [ ] | [ ] | [X] |
| Watering System _____                                      | [X] | [ ] | [ ] |
| 3. General Site Information:                               |     |     |     |
| Signage <u>LOCATED ON NEIL AVENUE</u>                      | [ ] | [X] | [ ] |
| Address Identification <u>ON SIGN</u>                      | [ ] | [X] | [ ] |
| Security Lights <u>LOCATED ABOVE DOORS AND AT CANOPIES</u> | [ ] | [X] | [ ] |
| Street Lights <u>NEW LIGHTS ALONG NEIL AVENUE</u>          | [ ] | [X] | [ ] |
| Drainage <u>NO PROBLEMS OBSERVED</u>                       | [ ] | [X] | [ ] |
| Storm Drains <u>NO PROBLEMS</u>                            | [ ] | [X] | [ ] |

**B. COMMENTS:**

BUILDING OCCUPANTS REPORTED THAT THERE HAVE BEEN SEVERAL INSTANCES OF TRIPPING AT THE WEST SIDEWALK LEADING UP TO THE ENTRANCE BECAUSE OF UNEVEN WALK. THE FRONT (EAST) WALKS AND PLAZA WERE RENOVATED AS A PART OF THE DREESE LAB ADDITION. THE WEST LAWN IS BEING REGRADED AND PLANTED.

**The Ohio State University  
Department of Physical Facilities**

**BUILDING AUDIT METHODOLOGY**

1. BUILDING AUDIT PROGRAM OBJECTIVE

The primary objective of this program is to provide a building-by-building inventory and current list of building maintenance deficiencies. This analysis is limited to the buildings for which the Department of Physical Facilities has budgetary responsibility. These audits will be used to establish corrective maintenance projects and budget cost estimates.

2. BUILDING AUDIT APPROACH

A five-step procedure is used to meet the program objectives:

1. Collect Historical and Inventory Data on each building.
2. Interview Building Occupants.
3. Perform a Building Inspection.
4. Complete Building Evaluation Forms.
5. Issue Written Report.

3. DATA ORGANIZATION

The data collected is stored by hard copy with field notes in a building file established for each building. The report data is being stored in a database program that allows retrieval of specific data as it is needed. The "Building Evaluation" forms contain ratings for the condition of each building component and a description of any deficiencies for those components. The "Building Information" forms provide data on the utilities to the buildings and the type of systems in each building.

4. COST ESTIMATES

Costs are for budgeting purposes only and are based on The Means Standard Construction Cost data, auditor experience, industry sources and OSU project cost data. Costs are reported current to the year of the audit. The building component values assigned in the "Building Evaluation" forms are not cost estimates. These values are calculated from the replacement cost provided by The Office of Campus Planning and Space Utilization for each OSU building.

5. LIMITATIONS

(1) All inspections are visual and do not include physical tests, instrumentation or metering measurements, sampling, or monitoring.

(2) Only random typical offices or laboratories are entered. Typical spaces are deemed to be representative of average conditions throughout each building.

(3) The scope of the analysis does not include complete OSHA, energy, or physical impaired access study. Buildings and components are inspected for condition and general safety requirements rather than specialized code conformance.

(4) It is assumed that the buildings inspected were approved by the State of

Ohio Division of Factory and Building Inspection at the time of construction. The recommendations listed in the reports are not an attempt to bring these existing buildings up to present day code standards. Rather, the intent is to eliminate obvious problems and to upgrade the buildings in a reasonable manner regarding occupant safety.

(5) Cost estimates are in current year dollars and include contractor mark-ups, construction administration costs, and architectural/engineering costs where applicable. Escalation factors must be applied for future work. Combining of projects should serve to decrease costs. These estimates are strictly for purposes of budgeting, and final pricing will be required when the specific scope of work for the project is defined.

(6) The building inspections are defined to include the following:

- (a) General repainting, redecorating, wholesale replacement of building and system components, on-going maintenance, replacement and renovation projects.
- (b) Exterior building walls and attached items.
- (c) Entrance steps at all entries, ramps outside the buildings, and a limited evaluation of plantings around the building exterior.

(7) The building inspections do not include:

- (a) Movable furniture.
- (b) Fixed equipment inside the buildings that is installed and maintained by a specific academic department or using agency.
- (c) Utility lines supplying the buildings.

(8) The program needs of the using Department are assumed to be satisfied. No consideration has been given to anticipate any changes in current occupant space needs.

## ABBREVIATIONS

|           |   |
|-----------|---|
| ATT.....  | ATTENTION   |
| BLDG..... | BUILDING  |
| BUR.....  | BUILT UP ROOF                                       |
| COND..... | CONDENSATE WATER                                    |
| DD.....   | DUAL DUCT AIR HANDLING SYSTEM                       |
| DDHV..... | DUAL DUCT HIGH VELOCITY                             |
| DHWR..... | DOMESTIC HOT WATER RETURN                           |
| DHWS..... | DOMESTIC HOT WATER SUPPLY                           |
| DX.....   | DIRECT EXPANSION AIR CONDITIONER                    |
| FPM.....  | FEET PER MINUTE                                     |
| HID.....  | HIGH INTENSITY DISCHARGE LIGHT                      |
| HPS.....  | HIGH PRESSURE STEAM (125 PSI)                       |
| HVAC..... | HEATING, VENTILATING AND<br>AIR CONDITIONING SYSTEM |
| KV.....   | KILOVOLTS   |
| KVA.....  | KILOVOLTS AMPS                                      |
| KW.....   | KILOWATTS   |
| LC.....   | LIQUID COOLED                                       |
| LPS.....  | LOW PRESSURE STEAM (15 PSI)                         |
| MPS.....  | MEDIUM PRESSURE STEAM (50 PSI)                      |
| MZ.....   | MULTIZONE AIR HANDLING SYSTEM                       |
| N/A.....  | NOT APPLICABLE                                      |
| PSI.....  | POUNDS PER SQUARE INCH                              |
| RM.....   | ROOM  |
| SAT.....  | SATISFACTORY  |
| SR.....   | STEAM RETURN LINE                                   |
| SS.....   | STEAM SUPPLY LINE                                   |
| TR.....   | TERMINAL REHEAT AIR HANDLING SYSTEM                 |
| V.....    | VOLTS   |
| VAV.....  | VARIABLE AIR VOLUME SYSTEM                          |

**APPENDIX**  
Reduced Scale Building Floor Plans  
C-1 Building Space Assignments